

FIELD INSPECTION REPORT

Project Name:	Mountain Valley Pipeline	Inspector:	Marshall Willis
Inspection Date:	Monday, March 15, 2021	Project Contact:	Brian Clauto, Cory Chalmers
Spread H: Roanoke County	STA 12942+90 – 12982+00 MVP-RO-287 MVP-RO-288	Weather:	Dry

ACTIVE STAGE OF CONSTRUCTION: (Check all that apply)

- | | | | | |
|---|--|--|--|---|
| ☐ Tree Felling | ☐ Clearing/Grubbing | ☐ Grading | ☐ Trenching | ☐ Stringing/Welding |
| ☐ Lowering/Backfilling | ☐ Final Restoration | ☐ Temp. Stabilization | ☐ Perm. Stabilization | ☒ Dormant |

- | | Yes | No | N/A |
|--|-------------------------------------|-------------------------------------|--------------------------|
| 1. Are controls installed and implemented in accordance with the approved erosion and sediment control plan and stormwater management plans? | ☒ | ☐ | ☐ |
| 2. Are all control measures properly maintained in effective operating condition in accordance with good engineering practices and, where applicable, manufacturer specifications? | ☒ | ☐ | ☐ |
| 3. Areas of offsite sediment deposition observed? | ☐ | ☒ | ☐ |

Comments: Inspected the following resources: S-Y7, S-Y8 and W-Y2.

Recommended Corrective Action: N/A

Deadline: N/A

The recommended corrective action deadline date applies to all conditions noted on this report unless otherwise noted. If listed condition(s) currently constitute non-compliance and/or corrective actions are not completed by the deadline, other enforcement actions may be issued to the entity responsible for ensuring compliance on the above project.

Inspector Signature:



Date: Monday, March 15, 2021

FIELD INSPECTION PHOTO LOG

Project Name: Mountain Valley Pipeline

Date: Monday, March 15, 2021

Figure 1: STA 12975+00 – Controls in place and functioning properly. Area stabilized with hydro-mulch and straw.
BRG: 142°SE (T) LAT: 37.130313 LON: -80.136784 ±16ft ALT: 2680ft



Figure 2: STA 12965+00 – Controls in place and functioning properly. Area stabilized with erosion control matting.
BRG: 14°N (T) LAT: 37.132431 LON: -80.137334 ±98ft ALT: 2758ft



Figure 3: STA 12956+00 – Controls in place and functioning properly. Area stabilized with hydro-mulch and straw.
BRG: 333°NW (T) LAT: 37.134928 LON: -80.137904 ±16ft ALT: 2648ft



Figure 4: STA 12950+00 – Controls in place and functioning properly. Area stabilized with hydro-mulch and straw.
BRG: 358°N (T) LAT: 37.146534 LON: -80.124510 ±7851ft ALT: 2640ft

