

FIELD INSPECTION REPORT

Project Name:	Mountain Valley Pipeline	Inspector:	Marshall Willis
Inspection Date:	Friday, March 12, 2021	Project Contact:	Brian Clauto, Cory Chalmers
Spread I: Franklin County	STA 14171+36 – 14209+75	Weather:	Dry

ACTIVE STAGE OF CONSTRUCTION: (Check all that apply)

- ☐ Tree Felling
 ☐ Clearing/Grubbing
 ☐ Grading
 ☐ Trenching
 ☐ Stringing/Welding
☐ Lowering/Backfilling
 ☐ Final Restoration
 ☒ Temp. Stabilization
 ☐ Perm. Stabilization
 ☒ Dormant

- | | | Yes | No | N/A |
|----|---|-------------------------------------|-------------------------------------|--------------------------|
| 1. | Are controls installed and implemented in accordance with the approved erosion and sediment control plan and stormwater management plans? | <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> |
| 2. | Are all control measures properly maintained in effective operating condition in accordance with good engineering practices and, where applicable, manufacturer specifications? | <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> |
| 3. | Areas of offsite sediment deposition observed? | <input type="checkbox"/> | <input checked="" type="checkbox"/> | <input type="checkbox"/> |

Comments: Inspected the following resources: S-KL52, S-KL54 and S-F8.

Recommended Corrective Action: N/A

Deadline: N/A

The recommended corrective action deadline date applies to all conditions noted on this report unless otherwise noted. If listed condition(s) currently constitute non-compliance and/or corrective actions are not completed by the deadline, other enforcement actions may be issued to the entity responsible for ensuring compliance on the above project.

Inspector Signature:



Date: Friday, March 12, 2021

FIELD INSPECTION PHOTO LOG

Project Name: Mountain Valley Pipeline

Date: Friday, March 12, 2021

Figure 1: Stream S-KL52 – Controls in place and functioning properly. Area stabilized with straw and hydro-mulch.

BRG: 242°SW (T) LAT: 37.050713 LON: -79.842646 ±7720ft ALT: 1028ft



A-KL52

Figure 2: STA 14178+00 – Controls in place and functioning properly. Area stabilized with straw and hydro-mulch.

BRG: 83°E (T) LAT: 37.058533 LON: -79.844518 ±16ft ALT: 990ft



14178

Figure 3: Stream S-KL54 – Controls in place and functioning properly. Area stabilized with straw and hydro-mulch.

BRG: 68°NE (T) LAT: 37.059521 LON: -79.840691 ±32ft ALT: 922ft



S-KL43b

Figure 4: STA 14200+00 – Controls in place and functioning properly. Area stabilized with straw and hydro-mulch.

BRG: 153°SE (T) LAT: 37.060355 LON: -79.838366 ±98ft ALT: 970ft



14200