

## FIELD INSPECTION REPORT

<b>Project Name:</b>	Mountain Valley Pipeline	<b>Inspector:</b>	Marshall Willis
<b>Inspection Date:</b>	Wednesday, March 10, 2021	<b>Project Contact:</b>	Brian Clauto, Cory Chalmers
<b>Spread I: Franklin County Pittsylvania County</b>	STA 15480+67 – 15447+00 STA 14233+12 – 14250+00 MVP-MLV-AR-32	<b>Weather:</b>	Dry

**ACTIVE STAGE OF CONSTRUCTION:** (Check all that apply)

- ☐ Tree Felling     
 ☐ Clearing/Grubbing     
 ☐ Grading     
 ☐ Trenching     
 ☐ Stringing/Welding  
☐ Lowering/Backfilling     
 ☐ Final Restoration     
 ☐ Temp. Stabilization     
 ☐ Perm. Stabilization     
☒ Dormant

- |  | Yes                                 | No                                  | N/A                      |
|--|-------------------------------------|-------------------------------------|--------------------------|
| 1. Are controls installed and implemented in accordance with the approved erosion and sediment control plan and stormwater management plans?                                       | <input checked="" type="checkbox"/> | <input type="checkbox"/>            | <input type="checkbox"/> |
| 2. Are all control measures properly maintained in effective operating condition in accordance with good engineering practices and, where applicable, manufacturer specifications? | <input type="checkbox"/>            | <input checked="" type="checkbox"/> | <input type="checkbox"/> |
| 3. Areas of offsite sediment deposition observed?  | <input type="checkbox"/>            | <input checked="" type="checkbox"/> | <input type="checkbox"/> |

Comments: Inspected the following resources: N/A.

**Routine Maintenance:** *(72-Hour Deadline from Notification)*

- STA 14235+00: Re-stabilize staging area.
- MVP-MLV-AR-32: RCE maintenance needed.

**Recommended Corrective Action:** Maintain and install all controls per the approved PSS&S.

**Deadline:** Within 72-Hour of Notification

The recommended corrective action deadline date applies to all conditions noted on this report unless otherwise noted. If listed condition(s) currently constitute non-compliance and/or corrective actions are not completed by the deadline, other enforcement actions may be issued to the entity responsible for ensuring compliance on the above project.

**Inspector Signature:** Marshall Willis

**Date:** Wednesday, March 10, 2021

## FIELD INSPECTION PHOTO LOG

**Project Name:** Mountain Valley Pipeline

**Date:** Wednesday, March 10, 2021

**Figure 1: STA 15458+00** – Controls in place and functioning properly. Area stabilized with straw.

**BRG:** 280°W (T) **LAT:** 36.912720 **LON:** -79.484503 ±98ft **ALT:** 989ft



**Figure 2: STA 15454+00** – Controls in place and functioning properly. Area stabilized with straw.

**BRG:** 75°E (T) **LAT:** 36.912660 **LON:** -79.485563 ±3943ft **ALT:** 857ft



**Figure 3: MLV-AR-32** – RCE maintenance needed.

**BRG:** 15°N (T) **LAT:** 37.055729 **LON:** -79.829843 ±16ft **ALT:** 864ft



**Figure 4: STA 14235+00** – Re-stabilization of staging area needed.

**BRG:** 102°E (T) **LAT:** 37.055335 **LON:** -79.829681 ±16ft **ALT:** 860ft

