

FIELD INSPECTION REPORT

Project Name:	Mountain Valley Pipeline	Inspector:	Marshall Willis
Inspection Date:	Tuesday, March 9, 2021	Project Contact:	Brian Clauto, Cory Chalmers
Spread H: Montgomery County	STA 12445+19 – 12544+06	Weather:	Dry

ACTIVE STAGE OF CONSTRUCTION: (Check all that apply)

- ☐ Tree Felling
 ☐ Clearing/Grubbing
 ☐ Grading
 ☐ Trenching
 ☐ Stringing/Welding
☐ Lowering/Backfilling
 ☐ Final Restoration
 ☐ Temp. Stabilization
 ☐ Perm. Stabilization
 ☒ Dormant

- | | | Yes | No | N/A |
|----|---|-------------------------------------|-------------------------------------|--------------------------|
| 1. | Are controls installed and implemented in accordance with the approved erosion and sediment control plan and stormwater management plans? | ☒ | ☐ | ☐ |
| 2. | Are all control measures properly maintained in effective operating condition in accordance with good engineering practices and, where applicable, manufacturer specifications? | ☒ | ☐ | ☐ |
| 3. | Areas of offsite sediment deposition observed? | ☐ | ☒ | ☐ |

Comments: Inspected the following resources: S-EF19, W-KL58 and S-CD12b.

Recommended Corrective Action: N/A

Deadline: N/A

The recommended corrective action deadline date applies to all conditions noted on this report unless otherwise noted. If listed condition(s) currently constitute non-compliance and/or corrective actions are not completed by the deadline, other enforcement actions may be issued to the entity responsible for ensuring compliance on the above project.

Inspector Signature:



Date: Tuesday, March 9, 2021

FIELD INSPECTION PHOTO LOG

Project Name: Mountain Valley Pipeline

Date: Tuesday, March 9, 2021

Figure 1: STA 12530+00 – Controls in place and functioning properly. Area stabilized with erosion control matting.

BRG: 139°SE (T) **LAT:** 37.231710 **LON:** -80.168677 ±7667ft **ALT:** 1703ft



Figure 2: STA 12523+00 – Controls in place and functioning properly. Area stabilized with erosion control matting.

BRG: 324°NW (T) **LAT:** 37.215030 **LON:** -80.196913 ±16ft **ALT:** 1795ft



Figure 3: STA 12513+00 – Controls in place and functioning properly. Area stabilized with erosion control matting.

BRG: 202°S (T) **LAT:** 37.217838 **LON:** -80.197235 ±16ft **ALT:** 1898ft



Figure 4: STA 12502+00 – Controls in place and functioning properly. Area stabilized with erosion control matting.

BRG: 133°SE (T) **LAT:** 37.218252 **LON:** -80.200305 ±16ft **ALT:** 1727ft

