

FIELD INSPECTION REPORT

Project Name:	Mountain Valley Pipeline	Inspector:	Marshall Willis
Inspection Date:	Monday, March 29, 2021	Project Contact:	Brian Clauto, Cory Chalmers
Spread I: Pittsylvania County	STA 15853+73 – 16000+00 MVP-PI-340	Weather:	Wet

ACTIVE STAGE OF CONSTRUCTION: (Check all that apply)

- ☐ Tree Felling
 ☐ Clearing/Grubbing
 ☐ Grading
 ☐ Trenching
 ☐ Stringing/Welding
☐ Lowering/Backfilling
 ☐ Final Restoration
 ☐ Temp. Stabilization
 ☐ Perm. Stabilization
 ☒ Dormant

- | | | Yes | No | N/A |
|----|---|-------------------------------------|-------------------------------------|--------------------------|
| 1. | Are controls installed and implemented in accordance with the approved erosion and sediment control plan and stormwater management plans? | <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> |
| 2. | Are all control measures properly maintained in effective operating condition in accordance with good engineering practices and, where applicable, manufacturer specifications? | <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> |
| 3. | Areas of offsite sediment deposition observed? | <input type="checkbox"/> | <input checked="" type="checkbox"/> | <input type="checkbox"/> |

Comments: Inspected the following resources: S-B2, W-H26, S-H55, S-H54, S-GG11, W-H1, W-H2, S-H3, W-H3, S-H5, W-MM3, S-OO1 and S-OO2.

Recommended Corrective Action: N/A

Deadline: N/A

The recommended corrective action deadline date applies to all conditions noted on this report unless otherwise noted. If listed condition(s) currently constitute non-compliance and/or corrective actions are not completed by the deadline, other enforcement actions may be issued to the entity responsible for ensuring compliance on the above project.

Inspector Signature:



Date: Monday, March 29, 2021

FIELD INSPECTION PHOTO LOG

Project Name: Mountain Valley Pipeline

Date: Monday, March 29, 2021

Figure 1: STA 15857+00 – Controls in place and functioning properly. Area stabilized with straw and hydro-mulch.
BRG: 116°SE (T) LAT: 36.851358 LON: -79.384242 ±32ft ALT: 739ft



Figure 2: STA 15935+00 – Controls in place and functioning properly. Area stabilized with straw and hydro-mulch.
BRG: 167°S (T) LAT: 36.814334 LON: -79.356787 ±24673ft ALT: 638ft



Figure 3: STA 15970+00 – Controls in place and functioning properly. Area stabilized with straw and hydro-mulch.
BRG: 156°SE (T) LAT: 36.831479 LON: -79.358222 ±98ft ALT: 622ft



Figure 4: STA 15997+00 – Controls in place and functioning properly. Area stabilized with straw and hydro-mulch.
BRG: 263°W (T) LAT: 36.827102 LON: -79.351302 ±16ft ALT: 606ft

