

FIELD INSPECTION REPORT

Project Name:	Mountain Valley Pipeline	Inspector:	Marshall Willis
Inspection Date:	Friday, April 30, 2021	Project Contact:	Brian Clauto, Cory Chalmers
Spread I: Franklin County	STA 14454+22 – 14546+75 MVP-FR-317.01	Weather:	Dry

ACTIVE STAGE OF CONSTRUCTION: (Check all that apply)

- ☐ Tree Felling
 ☐ Clearing/Grubbing
 ☐ Grading
 ☐ Trenching
 ☐ Stringing/Welding
☐ Lowering/Backfilling
 ☐ Final Restoration
 ☐ Temp. Stabilization
 ☐ Perm. Stabilization
 ☒ Dormant

- | | | Yes | No | N/A |
|----|---|-------------------------------------|-------------------------------------|--------------------------|
| 1. | Are controls installed and implemented in accordance with the approved erosion and sediment control plan and stormwater management plans? | ☒ | ☐ | ☐ |
| 2. | Are all control measures properly maintained in effective operating condition in accordance with good engineering practices and, where applicable, manufacturer specifications? | ☒ | ☐ | ☐ |
| 3. | Areas of offsite sediment deposition observed? | ☐ | ☒ | ☐ |

Comments: Inspected the following resources: S-G22, S-G21, S-G23, S-G20, S-G18 and S-G17.

Recommended Corrective Action: N/A

Deadline: N/A

The recommended corrective action deadline date applies to all conditions noted on this report unless otherwise noted. If listed condition(s) currently constitute non-compliance and/or corrective actions are not completed by the deadline, other enforcement actions may be issued to the entity responsible for ensuring compliance on the above project.

Inspector Signature:



Date: Friday, April 30, 2021

FIELD INSPECTION PHOTO LOG

Project Name: Mountain Valley Pipeline

Date: Friday, April 30, 2021

Figure 1: STA 14469+00 – Controls in place and functioning properly.

BRG: 131°SE (T) **LAT:** 37.023637 **LON:** -79.765274 ±16ft **ALT:** 1067ft



14469

Figure 2: STA 14493+00 – Controls in place and functioning properly.

BRG: 144°SE (T) **LAT:** 37.018499 **LON:** -79.760867 ±16ft **ALT:** 1006ft



13393

Figure 3: STA 14505+00 – Controls in place and functioning properly.

BRG: 147°SE (T) **LAT:** 37.015174 **LON:** -79.758410 ±16ft **ALT:** 852ft



14505

Figure 4: STA 14538+00 – Controls in place and functioning properly.

BRG: 144°SE (T) **LAT:** 37.007684 **LON:** -79.754155 ±16ft **ALT:** 1036ft



14538