

FIELD INSPECTION REPORT

Project Name:	Mountain Valley Pipeline	Inspector:	Marshall Willis
Inspection Date:	Thursday, April 29, 2021	Project Contact:	Brian Clauto, Cory Chalmers
Spread H: Franklin County	STA 13342+67 – 13415+51	Weather:	Dry

ACTIVE STAGE OF CONSTRUCTION: (Check all that apply)

- ☐ Tree Felling
 ☐ Clearing/Grubbing
 ☐ Grading
 ☐ Trenching
 ☐ Stringing/Welding
☐ Lowering/Backfilling
 ☐ Final Restoration
 ☐ Temp. Stabilization
 ☐ Perm. Stabilization
 ☒ Dormant

- | | | Yes | No | N/A |
|----|---|-------------------------------------|-------------------------------------|--------------------------|
| 1. | Are controls installed and implemented in accordance with the approved erosion and sediment control plan and stormwater management plans? | <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> |
| 2. | Are all control measures properly maintained in effective operating condition in accordance with good engineering practices and, where applicable, manufacturer specifications? | <input type="checkbox"/> | <input checked="" type="checkbox"/> | <input type="checkbox"/> |
| 3. | Areas of offsite sediment deposition observed? | <input type="checkbox"/> | <input checked="" type="checkbox"/> | <input type="checkbox"/> |

Comments: Inspected the following resources: S-RR08, S-RR09, S-RR11, S-IJ1, S-IJ2, W-IJ1, S-IJ3 and W-IJ2-PEM.

Routine Maintenance: (*72-Hour Deadline from Notification*)

- STA 13369+00: Re-stabilize area.

Recommended Corrective Action: Maintain and install all controls per the approved PSS&S.

Deadline: Within 72-Hour of Notification

The recommended corrective action deadline date applies to all conditions noted on this report unless otherwise noted. If listed condition(s) currently constitute non-compliance and/or corrective actions are not completed by the deadline, other enforcement actions may be issued to the entity responsible for ensuring compliance on the above project.

Inspector Signature: Marshall Willis

Date: Thursday, April 29, 2021

FIELD INSPECTION PHOTO LOG

Project Name: Mountain Valley Pipeline

Date: Thursday, April 29, 2021

Figure 1: STA 13403+00 – Controls in place and functioning properly.

BRG: 107°E (T) LAT: 37.071306 LON: -79.967104 ±27803ft ALT: 1579ft



Figure 2: STA 13369+00 – Re-stabilization needed.

BRG: 17°N (T) LAT: 37.101517 LON: -80.035772 ±16ft ALT: 1758ft



Figure 3: STA 13455+00 – Controls in place and functioning properly. Area stabilized with erosion matting.

BRG: 299°NW (T) LAT: 37.101667 LON: -80.040218 ±164ft ALT: 1530ft



Figure 4: Stream S-RR11 – Controls in place and functioning properly.

BRG: 320°NW (T) LAT: 37.100946 LON: -80.039593 ±32ft ALT: 1491ft

