

FIELD INSPECTION REPORT

Project Name:	Mountain Valley Pipeline	Inspector:	Marshall Willis
Inspection Date:	Friday, April 23, 2021	Project Contact:	Brian Clauto, Cory Chalmers
Spread H: Roanoke County Franklin County	STA 12994+02 – 13065+00 MVP-FR-290	Weather:	Dry

ACTIVE STAGE OF CONSTRUCTION: (Check all that apply)

- | | | | | |
|---|--|--|--|---|
| ☐ Tree Felling | ☐ Clearing/Grubbing | ☐ Grading | ☐ Trenching | ☐ Stringing/Welding |
| ☐ Lowering/Backfilling | ☐ Final Restoration | ☐ Temp. Stabilization | ☐ Perm. Stabilization | ☒ Dormant |

- | | Yes | No | N/A |
|--|-------------------------------------|-------------------------------------|--------------------------|
| 1. Are controls installed and implemented in accordance with the approved erosion and sediment control plan and stormwater management plans? | ☒ | ☐ | ☐ |
| 2. Are all control measures properly maintained in effective operating condition in accordance with good engineering practices and, where applicable, manufacturer specifications? | ☐ | ☒ | ☐ |
| 3. Areas of offsite sediment deposition observed? | ☐ | ☒ | ☐ |

Comments: Inspected the following resources: S-G24, S-G25, W-ST2-PEM and S-H1.

Routine Maintenance: (72-Hour Deadline from Notification)

- STA 13045+00 to 13046+00: Re-stabilize area and repair rill erosion.
- STA 13050+50 to 13051+00: Re-stabilize area and repair rill erosion.

Recommended Corrective Action: Maintain and install all controls per the approved PSS&S.

Deadline: Within 72-Hour of Notification

The recommended corrective action deadline date applies to all conditions noted on this report unless otherwise noted. If listed condition(s) currently constitute non-compliance and/or corrective actions are not completed by the deadline, other enforcement actions may be issued to the entity responsible for ensuring compliance on the above project.

Inspector Signature:



Date: Friday, April 23, 2021

FIELD INSPECTION PHOTO LOG

Project Name: Mountain Valley Pipeline

Date: Friday, April 23, 2021

Figure 1: STA 13020+00 – Controls in place and functioning properly.

BRG: 106°E (T) LAT: 37.125378 LON: -80.123762 ±32ft ALT: 2761ft



Figure 2: STA 13045+00 to 13046+00 – Re-stabilization needed.

BRG: 230°SW (T) LAT: 37.128335 LON: -80.115636 ±16ft ALT: 2746ft



Figure 3: STA 13050+50 to 13051+00 – Re-stabilization needed.

BRG: 295°NW (T) LAT: 37.128477 LON: -80.114067 ±16ft ALT: 2807ft



Figure 4: STA 13059+00 – Controls in place and functioning properly.

BRG: 108°E (T) LAT: 37.133961 LON: -80.115466 ±31832ft ALT: 2737ft

