

## FIELD INSPECTION REPORT

<b>Project Name:</b>	Mountain Valley Pipeline	<b>Inspector:</b>	Marshall Willis
<b>Inspection Date:</b>	Tuesday, April 20, 2021	<b>Project Contact:</b>	Brian Clauto, Cory Chalmers
<b>Spread H: Roanoke County</b>	STA 13000+00 – 13015+13 STA 12964+64 – 12980+00 STA 12690+43 – 12708+00 MVP-RO-288/280	<b>Weather:</b>	Dry

**ACTIVE STAGE OF CONSTRUCTION:** (Check all that apply)

- ☐ Tree Felling     
 ☐ Clearing/Grubbing     
 ☐ Grading     
 ☐ Trenching     
 ☐ Stringing/Welding  
☐ Lowering/Backfilling     
 ☐ Final Restoration     
 ☐ Temp. Stabilization     
 ☐ Perm. Stabilization     
☒ Dormant

- |  | Yes                                 | No                                  | N/A                      |
|--|-------------------------------------|-------------------------------------|--------------------------|
| 1. Are controls installed and implemented in accordance with the approved erosion and sediment control plan and stormwater management plans?                                       | <input checked="" type="checkbox"/> | <input type="checkbox"/>            | <input type="checkbox"/> |
| 2. Are all control measures properly maintained in effective operating condition in accordance with good engineering practices and, where applicable, manufacturer specifications? | <input checked="" type="checkbox"/> | <input type="checkbox"/>            | <input type="checkbox"/> |
| 3. Areas of offsite sediment deposition observed?  | <input type="checkbox"/>            | <input checked="" type="checkbox"/> | <input type="checkbox"/> |

Comments: Inspected the following resources: S-KL4, S-Q20 and W-Q11.

**Recommended Corrective Action:** N/A

**Deadline:** N/A

The recommended corrective action deadline date applies to all conditions noted on this report unless otherwise noted. If listed condition(s) currently constitute non-compliance and/or corrective actions are not completed by the deadline, other enforcement actions may be issued to the entity responsible for ensuring compliance on the above project.

**Inspector Signature:** Marshall Willis

**Date:** Tuesday, April 20, 2021

## FIELD INSPECTION PHOTO LOG

**Project Name:** Mountain Valley Pipeline

**Date:** Tuesday, April 20, 2021

**Figure 1: STA 13012+50** – Controls in place and functioning properly.

**BRG:** 329°NW (T) **LAT:** 37.125929 **LON:** -80.125374 ±16ft **ALT:** 2681ft



**Figure 2: STA 12972+00** – Controls in place and functioning properly.

**BRG:** 158°S (T) **LAT:** 37.130657 **LON:** -80.136966 ±16ft **ALT:** 2734ft



**Figure 3: STA 12693+00** – Controls in place and functioning properly.

**BRG:** 121°SE (T) **LAT:** 37.136277 **LON:** -80.133465 ±40520ft **ALT:** 2762ft



**Figure 4: STA 12705+00** – Controls in place and functioning properly.

**BRG:** 151°SE (T) **LAT:** 37.190446 **LON:** -80.153365 ±98ft **ALT:** 3364ft

