

FIELD INSPECTION REPORT

Project Name:	Mountain Valley Pipeline	Inspector:	Marshall Willis
Inspection Date:	Thursday, April 15, 2021	Project Contact:	Brian Clauto, Cory Chalmers
Spread I: Pittsylvania County	STA 15370+62 – 15487+60	Weather:	Wet

ACTIVE STAGE OF CONSTRUCTION: (Check all that apply)

- ☐ Tree Felling
 ☐ Clearing/Grubbing
 ☐ Grading
 ☐ Trenching
 ☐ Stringing/Welding
☐ Lowering/Backfilling
 ☐ Final Restoration
 ☐ Temp. Stabilization
 ☐ Perm. Stabilization
 ☒ Dormant

- | | | Yes | No | N/A |
|----|---|-------------------------------------|-------------------------------------|--------------------------|
| 1. | Are controls installed and implemented in accordance with the approved erosion and sediment control plan and stormwater management plans? | ☒ | ☐ | ☐ |
| 2. | Are all control measures properly maintained in effective operating condition in accordance with good engineering practices and, where applicable, manufacturer specifications? | ☒ | ☐ | ☐ |
| 3. | Areas of offsite sediment deposition observed? | ☐ | ☒ | ☐ |

Comments: Inspected the following resources: S-G6, S-G5, S-G4, W-B3, S-G3 and S-CC16.

Recommended Corrective Action: N/A

Deadline: N/A

The recommended corrective action deadline date applies to all conditions noted on this report unless otherwise noted. If listed condition(s) currently constitute non-compliance and/or corrective actions are not completed by the deadline, other enforcement actions may be issued to the entity responsible for ensuring compliance on the above project.

Inspector Signature:



Date: Thursday, April 15, 2021

FIELD INSPECTION PHOTO LOG

Project Name: Mountain Valley Pipeline

Date: Thursday, April 15, 2021

Figure 1: STA 15372+00 – Controls in place and functioning properly. Area stabilized with Earth-Guard and straw.
BRG: 118°SE (T) LAT: 36.922348 LON: -79.510340 ±16ft ALT: 780ft



Figure 2: STA 15380+00 – Controls in place and functioning properly.
BRG: 103°E (T) LAT: 36.920934 LON: -79.507462 ±98ft ALT: 808ft



Figure 3: STA 15436+00 – Controls in place and functioning properly.
BRG: 116°SE (T) LAT: 36.915567 LON: -79.489889 ±4097ft ALT: 800ft



Figure 4: STA 15464+00 – Controls in place and functioning properly. Area stabilized with Earth-Guard and straw.
BRG: 295°NW (T) LAT: 36.912470 LON: -79.482609 ±98ft ALT: 1059ft

