

FIELD INSPECTION REPORT

Project Name:	Mountain Valley Pipeline	Inspector:	Marshall Willis
Inspection Date:	Wednesday, April 14, 2021	Project Contact:	Brian Clauto, Cory Chalmers
Spread H: Franklin County	STA 13061+44 – 13115+97 MVP-FR-290 MVP-FR-291	Weather:	Dry

ACTIVE STAGE OF CONSTRUCTION: (Check all that apply)

- | | | | | |
|---|--|--|--|---|
| ☐ Tree Felling | ☐ Clearing/Grubbing | ☐ Grading | ☐ Trenching | ☐ Stringing/Welding |
| ☐ Lowering/Backfilling | ☐ Final Restoration | ☐ Temp. Stabilization | ☐ Perm. Stabilization | ☒ Dormant |

- | | Yes | No | N/A |
|--|-------------------------------------|-------------------------------------|--------------------------|
| 1. Are controls installed and implemented in accordance with the approved erosion and sediment control plan and stormwater management plans? | ☒ | ☐ | ☐ |
| 2. Are all control measures properly maintained in effective operating condition in accordance with good engineering practices and, where applicable, manufacturer specifications? | ☒ | ☐ | ☐ |
| 3. Areas of offsite sediment deposition observed? | ☐ | ☒ | ☐ |

Comments: Inspected the following resources: S-G27, S-G26, W-RR4, S-RR18, W-RR3, S-RR16, W-KL41, W-EF3 and S-EF17.

Recommended Corrective Action: N/A

Deadline: N/A

The recommended corrective action deadline date applies to all conditions noted on this report unless otherwise noted. If listed condition(s) currently constitute non-compliance and/or corrective actions are not completed by the deadline, other enforcement actions may be issued to the entity responsible for ensuring compliance on the above project.

Inspector Signature: Marshall Willis

Date: Wednesday, April 14, 2021

FIELD INSPECTION PHOTO LOG

Project Name: Mountain Valley Pipeline

Date: Wednesday, April 14, 2021

Figure 1: STA 13110+00 – Controls in place and functioning properly.

BRG: 314°NW (T) **LAT:** 37.029336 **LON:** -80.013697 ±20174ft **ALT:** 2636ft



Figure 2: STA 13096+00 – Controls in place and functioning properly.

BRG: 257°W (T) **LAT:** 37.141071 **LON:** -80.114601 ±8783ft **ALT:** 3113ft



Figure 3: STA 13077+00 – Controls in place and functioning properly.

BRG: 237°SW (T) **LAT:** 37.156709 **LON:** -80.117076 ±24955ft **ALT:** 2976ft



Figure 4: STA 13063+00 – Controls in place and functioning properly.

BRG: 108°E (T) **LAT:** 37.140688 **LON:** -80.120142 ±8573ft **ALT:** 2674ft

