

## FIELD INSPECTION REPORT

<b>Project Name:</b>	Mountain Valley Pipeline	<b>Inspector:</b>	Marshall Willis
<b>Inspection Date:</b>	Tuesday, June 8, 2021	<b>Project Contact:</b>	Brian Clauto, Cory Chalmers
<b>Spread H:</b> Roanoke County Franklin County	STA 13159+13 – 13195+79 STA 12690+43 – 12715+79 MVP-RO-280 MVP-FR-292.01	<b>Weather:</b>	Dry

**ACTIVE STAGE OF CONSTRUCTION:** (Check all that apply)

- ☐ Tree Felling
 ☒ Clearing/Grubbing
 ☒ Grading
 ☐ Trenching
 ☐ Stringing/Welding  
☐ Lowering/Backfilling
 ☐ Final Restoration
 ☐ Temp. Stabilization
 ☐ Perm. Stabilization
 ☐ Dormant

- |  | Yes                                 | No                                  | N/A                      |
|--|-------------------------------------|-------------------------------------|--------------------------|
| 1. Are controls installed and implemented in accordance with the approved erosion and sediment control plan and stormwater management plans?                                       | <input checked="" type="checkbox"/> | <input type="checkbox"/>            | <input type="checkbox"/> |
| 2. Are all control measures properly maintained in effective operating condition in accordance with good engineering practices and, where applicable, manufacturer specifications? | <input checked="" type="checkbox"/> | <input type="checkbox"/>            | <input type="checkbox"/> |
| 3. Areas of offsite sediment deposition observed?  | <input type="checkbox"/>            | <input checked="" type="checkbox"/> | <input type="checkbox"/> |

Comments: Inspected the following resources: N/A

**Recommended Corrective Action:** N/A

**Deadline:** N/A

The recommended corrective action deadline date applies to all conditions noted on this report unless otherwise noted. If listed condition(s) currently constitute non-compliance and/or corrective actions are not completed by the deadline, other enforcement actions may be issued to the entity responsible for ensuring compliance on the above project.

**Inspector Signature:** Marshall Willis

**Date:** Tuesday, June 8, 2021

## FIELD INSPECTION PHOTO LOG

**Project Name:** Mountain Valley Pipeline

**Date:** Tuesday, June 8, 2021

**Figure 1: STA 12702+00** – Controls in place and functioning properly.  
BRG: 287°W (T) LAT: 37.190865 LON: -80.153850 ±32ft ALT: 3383ft



**Figure 2: STA 12708+00** – Controls in place and functioning properly.  
BRG: 182°S (T) LAT: 37.189582 LON: -80.151996 ±98ft ALT: 3069ft



**Figure 3: STA 13186+00** – Controls in place and functioning properly.  
BRG: 116°SE (T) LAT: 37.124961 LON: -80.077298 ±16ft ALT: 1487ft



**Figure 4: STA 13167+00** – Controls in place and functioning properly.  
BRG: 255°W (T) LAT: 37.108141 LON: -80.041600 ±15141ft ALT: 1549ft

