

FIELD INSPECTION REPORT

Project Name:	Mountain Valley Pipeline	Inspector:	Marshall Willis
Inspection Date:	Thursday, June 3, 2021	Project Contact:	Brian Clauto, Cory Chalmers
Spread G: Giles County	STA 10707+22 – 10749+71 Laydown Yard 029 MVP-GI-241.01/.04	Weather:	Dry

ACTIVE STAGE OF CONSTRUCTION: (Check all that apply)

- ☐ Tree Felling
 ☐ Clearing/Grubbing
 ☒ Grading
 ☐ Trenching
 ☐ Stringing/Welding
☐ Lowering/Backfilling
 ☐ Final Restoration
 ☐ Temp. Stabilization
 ☐ Perm. Stabilization
 ☐ Dormant

- | | Yes | No | N/A |
|--|-------------------------------------|-------------------------------------|--------------------------|
| 1. Are controls installed and implemented in accordance with the approved erosion and sediment control plan and stormwater management plans? | <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> |
| 2. Are all control measures properly maintained in effective operating condition in accordance with good engineering practices and, where applicable, manufacturer specifications? | <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> |
| 3. Areas of offsite sediment deposition observed? | <input type="checkbox"/> | <input checked="" type="checkbox"/> | <input type="checkbox"/> |


Comments: Inspected the following resources: S-G33 and W-Z11.

Recommended Corrective Action: N/A

Deadline: N/A

The recommended corrective action deadline date applies to all conditions noted on this report unless otherwise noted. If listed condition(s) currently constitute non-compliance and/or corrective actions are not completed by the deadline, other enforcement actions may be issued to the entity responsible for ensuring compliance on the above project.

Inspector Signature:



Date: Thursday, June 3, 2021

FIELD INSPECTION PHOTO LOG

Project Name: Mountain Valley Pipeline

Date: Thursday, June 3, 2021

Figure 1: Laydown Yard 029 – Controls in place and functioning properly.

BRG: 153°SE (T) LAT: 37.362826 LON: -80.676986 ±213ft ALT: 1712ft



Figure 2: STA 10723+00 – Controls in place and functioning properly.

BRG: 148°SE (T) LAT: 37.348082 LON: -80.643674 ±213ft ALT: 2411ft



Figure 3: STA 10730+00 – Controls in place and functioning properly.

BRG: 139°SE (T) LAT: 37.346974 LON: -80.642498 ±32ft ALT: 2334ft



Figure 4: STA 10738+00 – Controls in place and functioning properly.

BRG: 127°SE (T) LAT: 37.346188 LON: -80.639681 ±16ft ALT: 2354ft

