

FIELD INSPECTION REPORT

Project Name:	Mountain Valley Pipeline	Inspector:	Marshall Willis
Inspection Date:	Wednesday, June 2, 2021	Project Contact:	Brian Clauto, Cory Chalmers
Spread H: Roanoke County	STA 12690+43 – 12715+79 MVP-RO-280 MVP-RO-281	Weather:	Dry

ACTIVE STAGE OF CONSTRUCTION: (Check all that apply)

- Tree Felling
 Clearing/Grubbing
 Grading
 Trenching
 Stringing/Welding
 Lowering/Backfilling
 Final Restoration
 Temp. Stabilization
 Perm. Stabilization
 Dormant

- | | | Yes | No | N/A |
|----|---|-------------------------------------|-------------------------------------|--------------------------|
| 1. | Are controls installed and implemented in accordance with the approved erosion and sediment control plan and stormwater management plans? | <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> |
| 2. | Are all control measures properly maintained in effective operating condition in accordance with good engineering practices and, where applicable, manufacturer specifications? | <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> |
| 3. | Areas of offsite sediment deposition observed? | <input type="checkbox"/> | <input checked="" type="checkbox"/> | <input type="checkbox"/> |

Comments: Inspected the following resources: N/A

Recommended Corrective Action: N/A

Deadline: N/A

The recommended corrective action deadline date applies to all conditions noted on this report unless otherwise noted. If listed condition(s) currently constitute non-compliance and/or corrective actions are not completed by the deadline, other enforcement actions may be issued to the entity responsible for ensuring compliance on the above project.

Inspector Signature: _____



Date: Wednesday, June 2, 2021

FIELD INSPECTION PHOTO LOG

Project Name: Mountain Valley Pipeline

Date: Wednesday, June 2, 2021

Figure 1: STA 12692+00 – Controls in place and functioning properly.

BRG: 86°E (T) **LAT:** 37.191413 **LON:** -80.156897 ±16ft **ALT:** 3703ft



12692

Figure 2: STA 12704+00 – Controls in place and functioning properly.

BRG: 137°SE (T) **LAT:** 37.190555 **LON:** -80.153157 ±16ft **ALT:** 3356ft



12704

Figure 3: STA 12714+00 – Controls in place and functioning properly.

BRG: 168°S (T) **LAT:** 37.188013 **LON:** -80.151448 ±32ft **ALT:** 3140ft



12714

Figure 4: MVP-RO-281 – Controls in place and functioning properly. PPL installing MVP-RO-281.01.

BRG: 132°SE (T) **LAT:** 37.183112 **LON:** -80.147564 ±16ft **ALT:** 3145ft



281.01