

FIELD INSPECTION REPORT

Project Name:	Mountain Valley Pipeline	Inspector:	Marshall Willis
Inspection Date:	Thursday, May 20, 2021	Project Contact:	Brian Clauto, Cory Chalmers
Spread H: Montgomery County	STA 12284+75 – 12300+00 MVP-MN-276.03	Weather:	Dry

ACTIVE STAGE OF CONSTRUCTION: (Check all that apply)

- ☐ Tree Felling
 ☐ Clearing/Grubbing
 ☐ Grading
 ☐ Trenching
 ☐ Stringing/Welding
☐ Lowering/Backfilling
 ☐ Final Restoration
 ☐ Temp. Stabilization
 ☐ Perm. Stabilization
 ☒ Dormant

- | | | Yes | No | N/A |
|----|---|-------------------------------------|-------------------------------------|--------------------------|
| 1. | Are controls installed and implemented in accordance with the approved erosion and sediment control plan and stormwater management plans? | ☒ | ☐ | ☐ |
| 2. | Are all control measures properly maintained in effective operating condition in accordance with good engineering practices and, where applicable, manufacturer specifications? | ☒ | ☐ | ☐ |
| 3. | Areas of offsite sediment deposition observed? | ☐ | ☒ | ☐ |

Comments: Inspected the following resources: N/A

Recommended Corrective Action: N/A

Deadline: N/A

The recommended corrective action deadline date applies to all conditions noted on this report unless otherwise noted. If listed condition(s) currently constitute non-compliance and/or corrective actions are not completed by the deadline, other enforcement actions may be issued to the entity responsible for ensuring compliance on the above project.

Inspector Signature:



Date: Thursday, May 20, 2021

FIELD INSPECTION PHOTO LOG

Project Name: Mountain Valley Pipeline

Date: Thursday, May 20, 2021

Figure 1: STA 12285+00 – Controls in place and functioning properly. Area stabilized with erosion control matting.
BRG: 135°SE (T) LAT: 37.255202 LON: -80.230698 ±164ft ALT: 3149ft



Figure 2: STA 12290+00 – Controls in place and functioning properly. Area stabilized with erosion control matting.
BRG: 135°SE (T) LAT: 37.254997 LON: -80.228838 ±32ft ALT: 2407ft



Figure 3: STA 12292+00 – Controls in place and functioning properly. Area stabilized with erosion control matting.
BRG: 44°NE (T) LAT: 37.254998 LON: -80.228017 ±32ft ALT: 2281ft



Figure 4: STA 12295+00 – Controls in place and functioning properly. Area stabilized with erosion control matting.
BRG: 262°W (T) LAT: 37.255363 LON: -80.226695 ±328ft ALT: 2391ft

