

FIELD INSPECTION REPORT

Project Name:	Mountain Valley Pipeline	Inspector:	Marshall Willis
Inspection Date:	Thursday, May 13, 2021	Project Contact:	Brian Clauto, Cory Chalmers
Spread I: Franklin County	STA 15496+70 – 15619+48 MVP-FR-293.02	Weather:	Dry

ACTIVE STAGE OF CONSTRUCTION: (Check all that apply)

- ☐ Tree Felling
 ☐ Clearing/Grubbing
 ☐ Grading
 ☐ Trenching
 ☐ Stringing/Welding
☐ Lowering/Backfilling
 ☐ Final Restoration
 ☐ Temp. Stabilization
 ☐ Perm. Stabilization
 ☒ Dormant

- | | | Yes | No | N/A |
|----|---|-------------------------------------|-------------------------------------|--------------------------|
| 1. | Are controls installed and implemented in accordance with the approved erosion and sediment control plan and stormwater management plans? | <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> |
| 2. | Are all control measures properly maintained in effective operating condition in accordance with good engineering practices and, where applicable, manufacturer specifications? | <input type="checkbox"/> | <input checked="" type="checkbox"/> | <input type="checkbox"/> |
| 3. | Areas of offsite sediment deposition observed? | <input type="checkbox"/> | <input checked="" type="checkbox"/> | <input type="checkbox"/> |

Comments: Inspected the following resources: S-IJ8, S-IJ10, W-IJ8, S-KL2, S-II8, W-II8, S-II7, S-II9, S-II11, S-II12, S-GH6 and W-GH2.

Routine Maintenance: (72-Hour Deadline from Notification)

- STA 13561+00: Re-stabilization needed.

Recommended Corrective Action: Maintain and install all controls per the approved PSS&S.

Deadline: Within 72-Hour of Notification

The recommended corrective action deadline date applies to all conditions noted on this report unless otherwise noted. If listed condition(s) currently constitute non-compliance and/or corrective actions are not completed by the deadline, other enforcement actions may be issued to the entity responsible for ensuring compliance on the above project.

Inspector Signature: Marshall Willis

Date: Thursday, May 13, 2021

FIELD INSPECTION PHOTO LOG

Project Name: Mountain Valley Pipeline

Date: Thursday, May 13, 2021

Figure 1: STA 13438+00 – Controls in place and functioning properly.

BRG: 145°SE (T) LAT: 37.039086 LON: -79.984394 ±11184ft ALT: 1320ft



Figure 2: STA 13509+00 – Controls in place and functioning properly.

BRG: 264°W (T) LAT: 37.090206 LON: -80.001234 ±32ft ALT: 1399ft



Figure 3: STA 13540+00 – Controls in place and functioning properly.

BRG: 242°SW (T) LAT: 37.066149 LON: -79.940546 ±14131ft ALT: 1365ft



Figure 4: STA 13561+00 – Re-stabilization needed.

BRG: 295°NW (T) LAT: 37.092215 LON: -79.984258 ±32ft ALT: 1300ft

