

FIELD INSPECTION REPORT

Project Name:	Mountain Valley Pipeline	Inspector:	Marshall Willis
Inspection Date:	Wednesday, May 12, 2021	Project Contact:	Brian Clauto, Cory Chalmers
Spread H: Roanoke County	STA 12638+24 – 12690+43 MVP-RO-279.01	Weather:	Dry

ACTIVE STAGE OF CONSTRUCTION: (Check all that apply)

- ☐ Tree Felling
 ☐ Clearing/Grubbing
 ☐ Grading
 ☐ Trenching
 ☐ Stringing/Welding
☐ Lowering/Backfilling
 ☐ Final Restoration
 ☐ Temp. Stabilization
 ☐ Perm. Stabilization
 ☒ Dormant

- | | | Yes | No | N/A |
|----|---|-------------------------------------|-------------------------------------|--------------------------|
| 1. | Are controls installed and implemented in accordance with the approved erosion and sediment control plan and stormwater management plans? | ☒ | ☐ | ☐ |
| 2. | Are all control measures properly maintained in effective operating condition in accordance with good engineering practices and, where applicable, manufacturer specifications? | ☐ | ☒ | ☐ |
| 3. | Areas of offsite sediment deposition observed? | ☐ | ☒ | ☐ |

Comments: Inspected the following resources: S-IJ50.

Routine Maintenance: (72-Hour Deadline from Notification)
 - MVP-MN-276.03: P1 maintenance needed.

Recommended Corrective Action: Maintain and install all controls per the approved PSS&S.

Deadline: Within 72-Hour of Notification

The recommended corrective action deadline date applies to all conditions noted on this report unless otherwise noted. If listed condition(s) currently constitute non-compliance and/or corrective actions are not completed by the deadline, other enforcement actions may be issued to the entity responsible for ensuring compliance on the above project.

Inspector Signature: Marshall Willis

Date: **Wednesday, May 12, 2021**

FIELD INSPECTION PHOTO LOG

Project Name: Mountain Valley Pipeline

Date: Wednesday, May 12, 2021

Figure 1: STA 12643+00 – Controls in place and functioning properly. Area stabilized with erosion matting.
BRG: 55°NE (T) LAT: 37.193509 LON: -80.173139 ±7241ft ALT: 3435ft



Figure 2: Stream S-IJ50 – No ground disturbance present.

BRG: 30°NE (T) LAT: 37.194144 LON: -80.168150 ±98ft ALT: 2652ft



Figure 3: STA 12662+00 – SSF maintenance needed.

BRG: 12°N (T) LAT: 37.194615 LON: -80.166158 ±16ft ALT: 2884ft



Figure 4: STA 12662+00 – Controls in place and functioning properly. Area stabilized with erosion matting.

BRG: 95°E (T) LAT: 37.204435 LON: -80.163075 ±2555ft ALT: 2872ft

