

FIELD INSPECTION REPORT

Project Name:	Mountain Valley Pipeline	Inspector:	Marshall Willis
Inspection Date:	Monday, May 10, 2021	Project Contact:	Brian Clauto, Cory Chalmers
Spread I: Pittsylvania County	STA 15496+70 – 15619+48	Weather:	Dry

ACTIVE STAGE OF CONSTRUCTION: (Check all that apply)

- ☐ Tree Felling
 ☐ Clearing/Grubbing
 ☐ Grading
 ☐ Trenching
 ☐ Stringing/Welding
☐ Lowering/Backfilling
 ☐ Final Restoration
 ☐ Temp. Stabilization
 ☐ Perm. Stabilization
 ☒ Dormant

- | | | Yes | No | N/A |
|----|---|-------------------------------------|-------------------------------------|--------------------------|
| 1. | Are controls installed and implemented in accordance with the approved erosion and sediment control plan and stormwater management plans? | <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> |
| 2. | Are all control measures properly maintained in effective operating condition in accordance with good engineering practices and, where applicable, manufacturer specifications? | <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> |
| 3. | Areas of offsite sediment deposition observed? | <input type="checkbox"/> | <input checked="" type="checkbox"/> | <input type="checkbox"/> |

Comments: Inspected the following resources: S-CC13, S-CC14, W-CC2-PEM, S-MM8, W-MM8, S-CC15, S-CC8, S-CC5, S-CC9, S-CC10, S-MM10, W-MM9, S-CC1, W-MM8-PFO, W-MM8-PEM, S-CC3 and S-P5.

Recommended Corrective Action: N/A

Deadline: N/A

The recommended corrective action deadline date applies to all conditions noted on this report unless otherwise noted. If listed condition(s) currently constitute non-compliance and/or corrective actions are not completed by the deadline, other enforcement actions may be issued to the entity responsible for ensuring compliance on the above project.

Inspector Signature:



Date: Monday, May 10, 2021

FIELD INSPECTION PHOTO LOG

Project Name: Mountain Valley Pipeline

Date: Monday, May 10, 2021

Figure 1: STA 15500+00 – Controls in place and functioning properly. Area stabilized with Earth-Guard.
BRG: 149°SE (T) LAT: 36.906191 LON: -79.474077 ±16ft ALT: 927ft



Figure 2: STA 15548+00 – Controls in place and functioning properly. Area stabilized with Earth-Guard.
BRG: 304°NW (T) LAT: 36.898366 LON: -79.461016 ±32ft ALT: 796ft



Figure 3: STA 15554+00 – Controls in place and functioning properly. Area stabilized with Earth-Guard.
BRG: 118°SE (T) LAT: 36.896103 LON: -79.451283 ±13586ft ALT: 841ft



Figure 4: STA 15602+00 – Controls in place and functioning properly. Area stabilized with Earth-Guard.
BRG: 91°E (T) LAT: 36.892507 LON: -79.438882 ±13593ft ALT: 813ft

