

## FIELD INSPECTION REPORT

Project Name:	Mountain Valley Pipeline	Inspector:	Marshall Willis
Inspection Date:	Tuesday, May 4, 2021	Project Contact:	Brian Clauto, Cory Chalmers
Spread H: Montgomery County	STA 12298+39 – 12372+10 MVP-MN-276.03	Weather:	Dry

**ACTIVE STAGE OF CONSTRUCTION:** (Check all that apply)

- ☐ Tree Felling
 ☐ Clearing/Grubbing
 ☐ Grading
 ☐ Trenching
 ☐ Stringing/Welding  
☐ Lowering/Backfilling
 ☐ Final Restoration
 ☐ Temp. Stabilization
 ☐ Perm. Stabilization
 ☒ Dormant

- |    |                                                                                                                                                                                 | Yes                                 | No                                  | N/A                      |
|----|---------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|-------------------------------------|-------------------------------------|--------------------------|
| 1. | Are controls installed and implemented in accordance with the approved erosion and sediment control plan and stormwater management plans?                                       | <input checked="" type="checkbox"/> | <input type="checkbox"/>            | <input type="checkbox"/> |
| 2. | Are all control measures properly maintained in effective operating condition in accordance with good engineering practices and, where applicable, manufacturer specifications? | <input type="checkbox"/>            | <input checked="" type="checkbox"/> | <input type="checkbox"/> |
| 3. | Areas of offsite sediment deposition observed?                                                                                                                                  | <input type="checkbox"/>            | <input checked="" type="checkbox"/> | <input type="checkbox"/> |

Comments: Inspected the following resources: N/A.

**Routine Maintenance:** (72-Hour Deadline from Notification)  
 - MVP-MN-276.03: P1 maintenance needed.

**Recommended Corrective Action:** Maintain and install all controls per the approved PSS&S.

**Deadline:** Within 72-Hour of Notification

The recommended corrective action deadline date applies to all conditions noted on this report unless otherwise noted. If listed condition(s) currently constitute non-compliance and/or corrective actions are not completed by the deadline, other enforcement actions may be issued to the entity responsible for ensuring compliance on the above project.

**Inspector Signature:** Marshall Willis

**Date:** Tuesday, May 4, 2021

## FIELD INSPECTION PHOTO LOG

**Project Name:** Mountain Valley Pipeline

**Date:** Tuesday, May 4, 2021

**Figure 1: MVP-MN-276.03** – P1 repair needed.

**BRG:** 213°SW (T) **LAT:** 37.256830 **LON:** -80.227124 ±32ft **ALT:** 2706ft



**Figure 2: STA 12300+00** – Controls in place and functioning properly. Area stabilized with erosion matting.

**BRG:** 126°SE (T) **LAT:** 37.255826 **LON:** -80.226452 ±32ft **ALT:** 2563ft



**Figure 3: STA 12335+00** – Controls in place and functioning properly. Area stabilized with erosion matting.

**BRG:** 74°E (T) **LAT:** 37.252515 **LON:** -80.215471 ±98ft **ALT:** 1776ft



**Figure 4: STA 12351+00** – Controls in place and functioning properly. Area stabilized with erosion matting.

**BRG:** 169°S (T) **LAT:** 37.250875 **LON:** -80.210413 ±32ft **ALT:** 1567ft

