

FIELD INSPECTION REPORT

| | | | |
|--------------------------------------|---------------------------------|-------------------------|------------------------------------|
| Project Name: | Mountain Valley Pipeline | Inspector: | Marshall Willis |
| Inspection Date: | Monday, May 3, 2021 | Project Contact: | Brian Clauto, Cory Chalmers |
| Spread I: Franklin County | STA 14546+75 – 14599+25 | Weather: | Rainy |

ACTIVE STAGE OF CONSTRUCTION: (Check all that apply)

- ☐ Tree Felling
 ☐ Clearing/Grubbing
 ☐ Grading
 ☐ Trenching
 ☐ Stringing/Welding
☐ Lowering/Backfilling
 ☐ Final Restoration
 ☐ Temp. Stabilization
 ☐ Perm. Stabilization
 ☒ Dormant

- | | | Yes | No | N/A |
|----|---|-------------------------------------|-------------------------------------|--------------------------|
| 1. | Are controls installed and implemented in accordance with the approved erosion and sediment control plan and stormwater management plans? | <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> |
| 2. | Are all control measures properly maintained in effective operating condition in accordance with good engineering practices and, where applicable, manufacturer specifications? | <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> |
| 3. | Areas of offsite sediment deposition observed? | <input type="checkbox"/> | <input checked="" type="checkbox"/> | <input type="checkbox"/> |

Comments: Inspected the following resources: S-E18 and S-E17.

Recommended Corrective Action: N/A

Deadline: N/A

The recommended corrective action deadline date applies to all conditions noted on this report unless otherwise noted. If listed condition(s) currently constitute non-compliance and/or corrective actions are not completed by the deadline, other enforcement actions may be issued to the entity responsible for ensuring compliance on the above project.

Inspector Signature:



Date: Monday, May 3, 2021

FIELD INSPECTION PHOTO LOG

Project Name: Mountain Valley Pipeline

Date: Monday, May 3, 2021

Figure 1: STA 14547+00 – Controls in place and functioning properly.

BRG: 139°SE (T) LAT: 36.988801 LON: -79.739069 ±49215ft ALT: 1054ft



14547

Figure 2: Stream S-E18 – Controls in place and functioning properly around stream crossing.

BRG: 108°E (T) LAT: 37.001237 LON: -79.747906 ±236ft ALT: 883ft



S-E18

Figure 3: Stream S-E17 – Controls in place and functioning properly around stream crossing.

BRG: 102°E (T) LAT: 37.000551 LON: -79.742996 ±16ft ALT: 841ft



S-E17

Figure 4: STA 14598+00 – Controls in place and functioning properly.

BRG: 310°NW (T) LAT: 36.997788 LON: -79.738675 ±16ft ALT: 949ft



14598