

## FIELD INSPECTION REPORT

Project Name:	Mountain Valley Pipeline	Inspector:	Marshall Willis
Inspection Date:	Thursday, June 24, 2021	Project Contact:	Brian Clauto, Cory Chalmers
Spread I: Pittsylvania County	STA 15480+08 – 15584+23	Weather:	Dry

**ACTIVE STAGE OF CONSTRUCTION:** (Check all that apply)

- ☐ Tree Felling
 ☐ Clearing/Grubbing
 ☐ Grading
 ☐ Trenching
 ☐ Stringing/Welding  
☐ Lowering/Backfilling
 ☐ Final Restoration
 ☐ Temp. Stabilization
 ☐ Perm. Stabilization
 ☒ Dormant

- |    |                                                                                                                                                                                 | Yes                                 | No                                  | N/A                      |
|----|---------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|-------------------------------------|-------------------------------------|--------------------------|
| 1. | Are controls installed and implemented in accordance with the approved erosion and sediment control plan and stormwater management plans?                                       | <input checked="" type="checkbox"/> | <input type="checkbox"/>            | <input type="checkbox"/> |
| 2. | Are all control measures properly maintained in effective operating condition in accordance with good engineering practices and, where applicable, manufacturer specifications? | <input checked="" type="checkbox"/> | <input type="checkbox"/>            | <input type="checkbox"/> |
| 3. | Areas of offsite sediment deposition observed?                                                                                                                                  | <input type="checkbox"/>            | <input checked="" type="checkbox"/> | <input type="checkbox"/> |

Comments: Inspected the following resources: S-CC13, S-CC14, W-CC2-PEM, S-MM8, W-MM5, S-CC15, S-CC5, S-CC8, S-CC9, S-CC10 and S-CC11.

**Recommended Corrective Action:** N/A

**Deadline:** N/A

The recommended corrective action deadline date applies to all conditions noted on this report unless otherwise noted. If listed condition(s) currently constitute non-compliance and/or corrective actions are not completed by the deadline, other enforcement actions may be issued to the entity responsible for ensuring compliance on the above project.

**Inspector Signature:**



**Date:** Thursday, June 24, 2021

## FIELD INSPECTION PHOTO LOG

**Project Name:** Mountain Valley Pipeline

**Date:** Thursday, June 24, 2021

**Figure 1: STA 15481+00** – Controls in place and functioning properly.

**BRG:** 138°SE (T) **LAT:** 36.910441 **LON:** -79.477077 ±16ft **ALT:** 918ft



15481

**Figure 2: Stream S-CC15** – Controls in place and functioning properly.

**BRG:** 126°SE (T) **LAT:** 36.901907 **LON:** -79.466655 ±16ft **ALT:** 819ft



S-CC15

**Figure 3: STA 15502+00** – Controls in place and functioning properly. Area stabilized with Earth Guard and straw.

**BRG:** 95°E (T) **LAT:** 36.905465 **LON:** -79.472793 ±164ft **ALT:** 1086ft



15502

**Figure 4: STA 15580+00** – Controls in place and functioning properly. Area stabilized with Earth Guard and straw.

**BRG:** 315°NW (T) **LAT:** 36.894448 **LON:** -79.450240 ±32ft **ALT:** 820ft



15580