

FIELD INSPECTION REPORT

Project Name:	Mountain Valley Pipeline	Inspector:	Marshall Willis
Inspection Date:	Wednesday, June 23, 2021	Project Contact:	Brian Clauto, Cory Chalmers
Spread I: Franklin County	STA 13415+51 – 13450+00 STA 14010+76 – 14062+17 MVP-FR-293.02	Weather:	Dry

ACTIVE STAGE OF CONSTRUCTION: (Check all that apply)

- | | | | | |
|---|--|--|--|---|
| <input type="checkbox"/> Tree Felling | <input type="checkbox"/> Clearing/Grubbing | <input type="checkbox"/> Grading | <input type="checkbox"/> Trenching | <input type="checkbox"/> Stringing/Welding |
| <input type="checkbox"/> Lowering/Backfilling | <input type="checkbox"/> Final Restoration | <input type="checkbox"/> Temp. Stabilization | <input type="checkbox"/> Perm. Stabilization | <input checked="" type="checkbox"/> Dormant |

- | | Yes | No | N/A |
|--|-------------------------------------|-------------------------------------|--------------------------|
| 1. Are controls installed and implemented in accordance with the approved erosion and sediment control plan and stormwater management plans? | <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> |
| 2. Are all control measures properly maintained in effective operating condition in accordance with good engineering practices and, where applicable, manufacturer specifications? | <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> |
| 3. Areas of offsite sediment deposition observed? | <input type="checkbox"/> | <input checked="" type="checkbox"/> | <input type="checkbox"/> |


Comments: Inspected the following resources: S-IJ4, S-IJ8, S-KL39, S-YZ4 and S-YZ5.

Recommended Corrective Action: N/A

Deadline: N/A

The recommended corrective action deadline date applies to all conditions noted on this report unless otherwise noted. If listed condition(s) currently constitute non-compliance and/or corrective actions are not completed by the deadline, other enforcement actions may be issued to the entity responsible for ensuring compliance on the above project.

Inspector Signature:



Date: Wednesday, June 23, 2021

FIELD INSPECTION PHOTO LOG

Project Name: Mountain Valley Pipeline

Date: Wednesday, June 23, 2021

Figure 1: STA 14026+00 – Controls in place and functioning properly.

BRG: 354°N (T) **LAT:** 37.059603 **LON:** -79.882106 ±446ft **ALT:** 1144ft



Figure 2: STA 13435+00 – Controls in place and functioning properly.

BRG: 286°W (T) **LAT:** 37.090372 **LON:** -80.020888 ±16ft **ALT:** 1671ft



Figure 3: STA 13438+00 – Controls in place and functioning properly.

BRG: 114°SE (T) **LAT:** 37.090609 **LON:** -80.019966 ±98ft **ALT:** 1693ft



Figure 4: STA 13423+00 – Controls in place and functioning properly.

BRG: 115°SE (T) **LAT:** 37.091719 **LON:** -80.025659 ±16ft **ALT:** 1444ft

