

FIELD INSPECTION REPORT

Project Name:	Mountain Valley Pipeline	Inspector:	Marshall Willis
Inspection Date:	Tuesday, June 22, 2021	Project Contact:	Brian Clauto, Cory Chalmers
Spread H: Roanoke County Franklin County	STA 12725+00 – 12735+00 STA 13141+00 – 13145+00 MVP-RO-281/281.01 MVP-FR-292/292.01	Weather:	Rainy

ACTIVE STAGE OF CONSTRUCTION: (Check all that apply)

- | | | | | |
|---|---|--|--|--|
| <input type="checkbox"/> Tree Felling | <input checked="" type="checkbox"/> Clearing/Grubbing | <input checked="" type="checkbox"/> Grading | <input type="checkbox"/> Trenching | <input type="checkbox"/> Stringing/Welding |
| <input type="checkbox"/> Lowering/Backfilling | <input type="checkbox"/> Final Restoration | <input type="checkbox"/> Temp. Stabilization | <input type="checkbox"/> Perm. Stabilization | <input type="checkbox"/> Dormant |

- | | Yes | No | N/A |
|--|-------------------------------------|-------------------------------------|--------------------------|
| 1. Are controls installed and implemented in accordance with the approved erosion and sediment control plan and stormwater management plans? | <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> |
| 2. Are all control measures properly maintained in effective operating condition in accordance with good engineering practices and, where applicable, manufacturer specifications? | <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> |
| 3. Areas of offsite sediment deposition observed? | <input type="checkbox"/> | <input checked="" type="checkbox"/> | <input type="checkbox"/> |

Comments: Inspected the following resources: S-D14 and S-D17.

Recommended Corrective Action: N/A

Deadline: N/A

The recommended corrective action deadline date applies to all conditions noted on this report unless otherwise noted. If listed condition(s) currently constitute non-compliance and/or corrective actions are not completed by the deadline, other enforcement actions may be issued to the entity responsible for ensuring compliance on the above project.

Inspector Signature:



Date: Tuesday, June 22, 2021

FIELD INSPECTION PHOTO LOG

Project Name: Mountain Valley Pipeline

Date: Tuesday, June 22, 2021

Figure 1: STA 12692+00 – Controls in place and functioning properly.
BRG: 130°SE (T) LAT: 37.191400 LON: -80.156797 ±16ft ALT: 3723ft



Figure 2: STA 12734+00 – Controls in place and functioning properly.
BRG: 182°S (T) LAT: 37.184078 LON: -80.149100 ±213ft ALT: 3193ft



Figure 3: STA 12729+00 – Controls in place and functioning properly.
BRG: 189°S (T) LAT: 37.185128 LON: -80.148823 ±16ft ALT: 3329ft



Figure 4: STA 12724+00 – Controls in place and functioning properly.
BRG: 307°NW (T) LAT: 37.185643 LON: -80.149857 ±16ft ALT: 3375ft

