

FIELD INSPECTION REPORT

Project Name:	Mountain Valley Pipeline	Inspector:	Marshall Willis
Inspection Date:	Thursday, June 17, 2021	Project Contact:	Brian Clauto, Cory Chalmers
Spread H: Montgomery County	STA 12180+00 – 12194+23 STA 12420+43 – 12443+25 MVP-MN-274/279/279.02	Weather:	Dry

ACTIVE STAGE OF CONSTRUCTION: (Check all that apply)

- | | | | | |
|---|--|--|--|---|
| <input type="checkbox"/> Tree Felling | <input type="checkbox"/> Clearing/Grubbing | <input checked="" type="checkbox"/> Grading | <input type="checkbox"/> Trenching | <input type="checkbox"/> Stringing/Welding |
| <input type="checkbox"/> Lowering/Backfilling | <input type="checkbox"/> Final Restoration | <input type="checkbox"/> Temp. Stabilization | <input type="checkbox"/> Perm. Stabilization | <input checked="" type="checkbox"/> Dormant |

- | | Yes | No | N/A |
|--|-------------------------------------|-------------------------------------|--------------------------|
| 1. Are controls installed and implemented in accordance with the approved erosion and sediment control plan and stormwater management plans? | <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> |
| 2. Are all control measures properly maintained in effective operating condition in accordance with good engineering practices and, where applicable, manufacturer specifications? | <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> |
| 3. Areas of offsite sediment deposition observed? | <input type="checkbox"/> | <input checked="" type="checkbox"/> | <input type="checkbox"/> |


Comments: Inspected the following resources: S-C21 and S-NN16.

Recommended Corrective Action: N/A

Deadline: N/A

The recommended corrective action deadline date applies to all conditions noted on this report unless otherwise noted. If listed condition(s) currently constitute non-compliance and/or corrective actions are not completed by the deadline, other enforcement actions may be issued to the entity responsible for ensuring compliance on the above project.

Inspector Signature:



Date: Thursday, June 17, 2021

FIELD INSPECTION PHOTO LOG

Project Name: Mountain Valley Pipeline

Date: Thursday, June 17, 2021

Figure 1: STA 12185+00 – Controls in place and functioning properly.

BRG: 289°W (T) **LAT:** 37.234817 **LON:** -80.258111 ±6630ft **ALT:** 1294ft



Figure 2: Stream S-C21 – Controls in place and functioning properly along Bradshaw Creek crossing.

BRG: 39°NE (T) **LAT:** 37.252082 **LON:** -80.259042 ±98ft **ALT:** 1271ft



Figure 3: STA 12440+00 – Controls in place and functioning properly.

BRG: 214°SW (T) **LAT:** 37.232392 **LON:** -80.198871 ±16ft **ALT:** 1255ft



Figure 4: STA 12420+00 – Controls in place and functioning properly.

BRG: 36°NE (T) **LAT:** 37.236809 **LON:** -80.199536 ±16ft **ALT:** 1195ft

