STANDARDS & SPECIFICATIONS
SITE INSPECTION REPORT
LEVEL 1 *(FIELD REPORT)*

Project Name:	**Mountain Valley Pipeline**	S&S Program:	**Mountain Valley Pipeline (SS027)**
Inspector:	**Matthew Grant**	Inspection Date:	**Monday, August 4, 2025**
Project Contact:	**Cory Chalmers** **Brian Clauto**	Project Contact Email:	**Cory.chalmers@eqt.com** **Brian.clauto@eqt.com**
Spread G: **Giles County**	**STA 10800-10795+33,10790, 107959-10760, 10750-10749+50, 10885** **AR GI 241.02** **ATWS 1332, 1333**	Site Conditions:	**Dry**

ACTIVE STAGE OF CONSTRUCTION: (Check all that apply)

☐ Tree Felling ☐ Clearing/Grubbing ☐ Rough Grading ☐ Trenching ☐ Stringing/Welding

☐ Lowering/Backfilling ☒ Final Grading ☐ Temp. Stabilization ☐ Perm. Stabilization ☒ Dormant

		Yes	No	N/A
1.	Are controls installed and implemented in accordance with the approved erosion and sediment control plan and stormwater management plans?	☒	☐	☐
2.	Are all control measures properly maintained in effective operating condition in accordance with good engineering practices and, where applicable, manufacturer specifications?	☒	☐	☐
3.	Areas of offsite sediment deposition observed?	☐	☒	☐

> *Comments:* Inspected the following resources: S-Z14, S-Z13, S-A32
>
> **Routine Maintenance:** (*72-Hour Deadline from Notification*)
> -   N/A
> **Ineffective Controls:** (*24-Hour Deadline from Notification)*
> -   N/A
>
> **Corrective Action**: N/A

Deadline: N/A

The recommended corrective action deadline date applies to all conditions noted on this report unless otherwise noted. If listed condition(s) currently constitute non-compliance and/or corrective actions are not completed by the deadline, other enforcement actions may be issued to the entity responsible for ensuring compliance on the above project.

Inspector Signature: _____ *[signature]* _____

Date: **Monday, August 4, 2025**

FIELD INSPECTION PHOTO LOG

Fig. 1
STA 111240: reinstall perimeter control.

Fig. 2
Designated Crossing S-Z14: ECD remain in place.


Fig. 3
STA 10809: Area remains stabilized.

Fig. 4
STA 10885: Area remains stabilized.