



Project Name:	Mountain Valley Pipeline	Inspector:	Matthew Grant
Inspection Date:	Wednesday, June 29, 2022	Project Contact:	Brian Clauto
Spread H: Montgomery	ATWS 701, 1167, 1168, 703 AR MN-270.01 St12103+05-12190	Weather:	Dry

			St121	03+05-12190								
ACTIVE STAGE OF CONSTRUCTION: (Check all that apply)												
☐ Tree Felling		☐ Clearing/Grubbing		ing \square	☐ Grading		☐ Trenching			☐ Stringing/Welding		
	Lowering/Ba	ackfilling		Final Grading				on 🗵	□ Dormant			
										Yes	No	N/A
Are controls installed and implemented in accordance with the approved erosion and sediment control plan and stormwater management plans?												
		Are all control measures properly maintained in effective operating condition in accordance with good engineering practices and, where applicable, manufacturer specifications?								\boxtimes		
	3.	Areas of o	offsite s	sediment deposi	tion observe	d?					\boxtimes	
 <u>Comments:</u> Inspected the following resources: S-EF15, S-F17, S-F16a&b, S-C36, S-C31, W-C6, S-C25, S-C24 ECD's were in place and functioning at the designated crossings. 												
Routine Maintenance: (<u>72-Hour Deadline</u> from Notification) - N/A												
Ineffective Controls: (24-Hour Deadline from Notification) - N/A												
Recommended Corrective Action: N/A												

Deadline: N/A

The recommended corrective action deadline date applies to all conditions noted on this report unless otherwise noted. If listed condition(s) currently constitute non-compliance and/or corrective actions are not completed by the deadline, other enforcement actions may be issued to the entity responsible for ensuring compliance on the above project.

Inspector Signature:

Date: Wednesday, June 29, 2022

FIELD INSPECTION PHOTO LOG



Project Name: Mountain Valley Pipeline Date: Wednesday, June 29, 2022

Figure 1: Designated crossing S-C25, ECD's are in place.



Figure 2: Designated crossing S-C31, ECD's are in place.



• Figure 3: Designated crossing S-EF15, ECD's are in place.



• Figure 4: Designated crossing S-C36, ECD's are in place.

