

FIELD INSPECTION REPORT

Project Name:	Mountain Valley Pipeline	Inspector:	Marshall Willis
Inspection Date:	Tuesday, January 10, 2023	Project Contact:	Brian Clauto, Cory Chalmers
Spread I: Pittsylvania County	STA 15142+66 – 15221+11 MVP-PI-326	Weather:	Wet

ACTIVE STAGE OF CONSTRUCTION: (Check all that apply)

- ☐ Tree Felling
 ☐ Clearing/Grubbing
 ☐ Grading
 ☐ Trenching
 ☐ Stringing/Welding
☐ Lowering/Backfilling
 ☐ Final Restoration
 ☐ Temp. Stabilization
 ☐ Perm. Stabilization
 ☒ Dormant

- | | | Yes | No | N/A |
|----|---|-------------------------------------|-------------------------------------|--------------------------|
| 1. | Are controls installed and implemented in accordance with the approved erosion and sediment control plan and stormwater management plans? | ☒ | ☐ | ☐ |
| 2. | Are all control measures properly maintained in effective operating condition in accordance with good engineering practices and, where applicable, manufacturer specifications? | ☐ | ☒ | ☐ |
| 3. | Areas of offsite sediment deposition observed? | ☐ | ☒ | ☐ |

Comments: Inspected the following resources: S-F1, S-C7 and S-F2.

Recommended Corrective Action: Maintain and install all controls per the approved PSS&S.

Routine Maintenance: (72-Hour Deadline from Notification)

- STA 15169+50: WB Maintenance needed.

Deadline: Within 72-Hour of Notification

The recommended corrective action deadline date applies to all conditions noted on this report unless otherwise noted. If listed condition(s) currently constitute non-compliance and/or corrective actions are not completed by the deadline, other enforcement actions may be issued to the entity responsible for ensuring compliance on the above project.

Inspector Signature: Marshall Willis

Date: Tuesday, January 10, 2023

FIELD INSPECTION PHOTO LOG

Project Name: Mountain Valley Pipeline

Date: Tuesday, January 10, 2023

Figure 1: STA 15165+00 – Controls in place and functioning properly.



Figure 2: STA 15169+50 – WB Maintenance needed.



Figure 3: STA 15170+00 – Controls in place and functioning properly.



Figure 4: STA 15195+00 – Controls in place and functioning properly.

