

FIELD INSPECTION REPORT

Project Name:	Mountain Valley Pipeline	Inspector:	Marshall Willis
Inspection Date:	Friday, July 14, 2023	Project Contact:	Brian Clauto, Cory Chalmers
Spread H: Montgomery County	STA 12071+80 – 12132+73 MVP-MN-270	Weather:	Wet

ACTIVE STAGE OF CONSTRUCTION: (Check all that apply)

- ☐ Tree Felling
 ☐ Clearing/Grubbing
 ☐ Grading
 ☐ Trenching
 ☒ Stringing/Welding
☒ Lowering/Backfilling
 ☐ Final Restoration
 ☐ Temp. Stabilization
 ☐ Perm. Stabilization
 ☐ Other

- | | | Yes | No | N/A |
|----|---|-------------------------------------|-------------------------------------|--------------------------|
| 1. | Are controls installed and implemented in accordance with the approved erosion and sediment control plan and stormwater management plans? | <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> |
| 2. | Are all control measures properly maintained in effective operating condition in accordance with good engineering practices and, where applicable, manufacturer specifications? | <input type="checkbox"/> | <input checked="" type="checkbox"/> | <input type="checkbox"/> |
| 3. | Areas of offsite sediment deposition observed? | <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> |

Comments: Inspected the following resources: S-MM15, S-MM14, S-MM13, S-MM11, S-F15, S-F9-PFO, S-C36, W-C12, S-C33, S-C36 S-MM31 and S-C29.

Ineffective Controls: (24-Hour Deadline from Notification)

- STA 12076+00: Sediment off ROW. End Treatment overtopped.
- STA 12098+00: P1 repair needed.
- STA 12098+00: Re-stabilize cut slope.
- STA 12098+75: SSF undermined/or bypassed.
- STA 12098+75: Sediment impacting Stream S-MM13 from undermined or bypassed SSF.

Deadline: Within 24-Hour of Notification

The recommended corrective action deadline date applies to all conditions noted on this report unless otherwise noted. If listed condition(s) currently constitute non-compliance and/or corrective actions are not completed by the deadline, other enforcement actions may be issued to the entity responsible for ensuring compliance on the above project.

Inspector Signature:



Date: **Friday, July 14, 2023**

FIELD INSPECTION PHOTO LOG

Project Name: Mountain Valley Pipeline

Date: Friday, July 14, 2023

Figure 1: STA 12076+00 – Sediment off ROW. End treatment overtopped.



Figure 2: STA 12098+00 – P1 repair needed.



Figure 3: STA 12098+00 – Re-stabilize cut slope.



Figure 4: STA 12098+75 – SSF undermined or bypassed.



FIELD INSPECTION PHOTO LOG

Project Name: Mountain Valley Pipeline

Date: Friday, July 14, 2023

Figure 5: STA 12098+75 – SSF undermined or bypassed.



Figure 6: STA 12098+75 – Sediment impacting stream S-MM13 from undermined or bypassed SSF (Figure 5).

