

## FIELD INSPECTION REPORT

Project Name:	Mountain Valley Pipeline	Inspector:	Marshall Willis
Inspection Date:	Friday, March 8, 2024	Project Contact:	Brian Clauto, Cory Chalmers
Spread I: Franklin County	STA 13690+91 – 13784+80 MVP-FR-300	Weather:	Dry

**ACTIVE STAGE OF CONSTRUCTION:** (Check all that apply)

- ☐ Tree Felling
 ☐ Clearing/Grubbing
 ☐ Grading
 ☐ Trenching
 ☐ Stringing/Welding  
☐ Lowering/Backfilling
 ☐ Final Restoration
 ☐ Temp. Stabilization
 ☐ Perm. Stabilization
 ☒ Dormant

- |    |   | Yes                                 | No                                  | N/A                      |
|----|---|-------------------------------------|-------------------------------------|--------------------------|
| 1. | Are controls installed and implemented in accordance with the approved erosion and sediment control plan and stormwater management plans?                                       | <input checked="" type="checkbox"/> | <input type="checkbox"/>            | <input type="checkbox"/> |
| 2. | Are all control measures properly maintained in effective operating condition in accordance with good engineering practices and, where applicable, manufacturer specifications? | <input type="checkbox"/>            | <input checked="" type="checkbox"/> | <input type="checkbox"/> |
| 3. | Areas of offsite sediment deposition observed?  | <input type="checkbox"/>            | <input checked="" type="checkbox"/> | <input type="checkbox"/> |

Comments: Inspected the following resources: S-E28(2), W-E7, W-E8, S-E28(3), S-EF4, S-EF12, S-MM42 and S-RR15.

**Routine Maintenance:** (*72-Hour Deadline from Notification*)

- STA 13770+00: Restabilize area.
- STA 13778+00 to 13779+00: Restabilize area.
- STA 13780+00: Restabilize area.
- STA 13784+00/ATWS 569A: Restabilize area and repair rilling.
- 

**Ineffective Controls:** (*24-Hour Deadline from Notification*)

- STA 13692+00: Clean up and properly dispose of spilled fertilizer.

**Deadline:** Various - See Comments

The recommended corrective action deadline date applies to all conditions noted on this report unless otherwise noted. If listed condition(s) currently constitute non-compliance and/or corrective actions are not completed by the deadline, other enforcement actions may be issued to the entity responsible for ensuring compliance on the above project.

**Inspector Signature:**



**Date:** Friday, March 8, 2024

## FIELD INSPECTION PHOTO LOG

**Project Name:** Mountain Valley Pipeline

**Date:** Friday, March 8, 2024

**Figure 1: STA 13692+00** – Clean up and dispose of spilled fertilizer properly.

☉ 335°NW (T) ● 37.085868°N, 79.947989°W ±22ft ▲ 1132ft



**Figure 2: STA 13770+00** – Restabilize denuded areas.

☉ 258°W (T) ● 37.070953°N, 79.936942°W ±9ft ▲ 1092ft



**Figure 3: STA 13778+00 to 13779+00** – Restabilize denuded areas.

☉ 261°W (T) ● 37.069583°N, 79.934509°W ±13ft ▲ 1101ft



**Figure 4: STA 13780+00** – Restabilize denuded areas.

☉ 212°SW (T) ● 37.069709°N, 79.933686°W ±16ft ▲ 1110ft





## FIELD INSPECTION PHOTO LOG

**Project Name:** Mountain Valley Pipeline

**Date:** Friday, March 8, 2024

**Figure 5: STA 13784+00/ATWS 569A** – Repair rills and restabilize denuded areas.

☉ 226°SW (T) ● 37.069906°N, 79.932785°W ±13ft ▲ 1141ft



Repair rills Restabilize 72

13784 / atws 569A  
08 Mar 2024