



STANDARDS & SPECIFICATIONS SITE INSPECTION REPORT LEVEL 1 (FIELD REPORT)

Project Name:	Mountain Valley Pipeline	S&S Program:	Mountain Valley Pipeline (SS027)
Inspector:	Marshall Willis	Inspection Date:	Wednesday, July 24, 2024
Project Contact:	Cory Chalmers Brian Clauto	Project Contact Email:	cchalmers@equitransmidstream.com bclauto@equitransmidstream.com
Spread I: Franklin County	STA 14233+00 – STA 14249+00 STA 14800+00 – STA 14806+00 STA 14752+00 – STA 14767+00 MVP-FR-323 MVP-MLV-AR-32	Site Conditions:	Wet

ACTIVE STAGE OF CONSTRUCTION: (Check all that apply)

- ☐ Tree Felling ☐ Clearing/Grubbing ☐ Rough Grading ☐ Trenching ☐ Stringing/Welding
☐ Lowering/Backfilling ☐ Final Grading ☐ Temp. Stabilization ☒ Perm. Stabilization ☐ Other

- | | Yes | No | N/A |
|--|-------------------------------------|-------------------------------------|--------------------------|
| 1. Are controls installed and implemented in accordance with the approved erosion and sediment control plan and stormwater management plans? | <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> |
| 2. Are all control measures properly maintained in effective operating condition in accordance with good engineering practices and, where applicable, manufacturer specifications? | <input type="checkbox"/> | <input checked="" type="checkbox"/> | <input type="checkbox"/> |
| 3. Areas of offsite sediment deposition observed? | <input type="checkbox"/> | <input checked="" type="checkbox"/> | <input type="checkbox"/> |

Comments: Inspected the following resources: S-C19, S-F11 and S-H23.

Routine Maintenance: (72-Hour Deadline from Notification)

- STA 14249+00: Repair perm WB and restabilize.
- STA 14234+00: Restabilize perm WB above S-C19.

Ineffective Controls: (24-Hour Deadline from Notification)

- STA 14805+00: CFS undermined. Repair erosion and restabilize.

Corrective Action: Maintain and install all controls per the approved S&S.

Deadline: Various - See Comments

The recommended corrective action deadline date applies to all conditions noted on this report unless otherwise noted. If listed condition(s) currently constitute non-compliance and/or corrective actions are not completed by the deadline, other enforcement actions may be issued to the entity responsible for ensuring compliance on the above project.

Inspector Signature: 

Date: Wednesday, July 24, 2024

STANDARDS & SPECIFICATIONS

SITE INSPECTION REPORT

LEVEL 1 (FIELD REPORT)

FIELD INSPECTION PHOTO LOG

Fig. 1

STA 14234+00: Restabilize perm WB above S-C19.



Fig. 2

STA 14249+00: Repair perm WB and restabilize.



Fig. 3

STA 14805+00: CFS undermined. Repair erosion and restabilize.



Fig. 4

STA 14805+00: CFS undermined. Repair erosion and restabilize.

