

STANDARDS & SPECIFICATIONS SITE INSPECTION REPORT

LEVEL 1 (FIELD REPORT)

Project Name:	Mountain Valley Pipeline	S&S Program:	Mountain Valley Pipeline (SS027)			
Inspector:	Marshall Willis	Inspection Date:	Wednesday, August 28, 2024			
Project Contact:	Cory Chalmers Brian Clauto	Project Contact Email:	cchalmers@equitransmidstream.com bclauto@equitransmidstream.com			
Spread H: Montgomery County	STA 12445+00 - STA 12465+00 MVP-MLV-AR-28	Site Conditions:	Dry			

ACTI	ACTIVE STAGE OF CONSTRUCTION: (Check all that apply)													
	Tree Felling			Clearing/Grubbing		Rough Grading		Trenching		Stri	nging/Welding			
	Lowering/E	owering/Backfilling		Final Grading		Temp. Stabilization		Perm. Stabilization	\boxtimes	Oth	er			
									Yes	No	N/A			
	1.	1. Are controls installed and implemented in accordance with the approved erosion and sediment control plan and stormwater management plans?								\boxtimes				
	2.	2. Are all control measures properly maintained in effective operating condition in accordance with good engineering practices and, where applicable, manufacturer specifications?							\boxtimes					
	3. Areas of offsite sediment deposition observed?									\boxtimes				
	<u>Comments:</u> Inspected the following resources: S-CD12b and WKL58. Ineffective Controls: (<u>24-Hour Deadline</u> from Notification) - ATWS 645: Stabilize conveyance channel. Corrective Action: Maintain and install all controls per the approved S&S.													

Deadline: Within 24-Hour of Notification

The recommended corrective action deadline date applies to all conditions noted on this report unless otherwise noted. If listed condition(s) currently constitute non-compliance and/or corrective actions are not completed by the deadline, other enforcement actions may be issued to the entity responsible for ensuring compliance on the above project.

Inspector Signature:

Date: Wednesday, August 28, 2024



STANDARDS & SPECIFICATIONS SITE INSPECTION REPORT LEVEL 1 (FIELD REPORT)

FIELD INSPECTION PHOTO LOG

Fig. 1 ATWS 645: Stabilize conveyance channel.



Fig. 2 **ATWS 645:** Stabilize conveyance channel.



Fig. 3 MVP-MLV-AR-28: Controls in place and functioning properly.



Fig. 4
STA 12565+00: Controls in place and functioning properly.

