

STANDARDS & SPECIFICATIONS SITE INSPECTION REPORT

LEVEL 1 (FIELD REPORT)

Project Name:	Mountain Valley Pipeline	S&S Program:	Mountain Valley Pipeline (SS027)			
Inspector:	Marshall Willis	Inspection Date:	Thursday, August 15, 2024			
Project Contact:	Cory Chalmers Brian Clauto	Project Contact Email:	cchalmers@equitransmidstream.com bclauto@equitransmidstream.com			
Spread H: Roanoke County Franklin County	STA 12760+00 - STA 12763+00 STA 13260+00 - STA 13264+00 MVP-RO-282 MVP-FR-293.01	Site Conditions:	Dry			

ACT	ACTIVE STAGE OF CONSTRUCTION: (Check all that apply)													
	Tree Felling		☐ Clearing/Grubbing			☐ Rough Grading		Trenching		Stri	nging/Welding			
	Lowering/Backfilling			Final Grading		Temp. Stabilization	\boxtimes	Perm. Stabilization		Other				
									Yes	No	N/A			
	Are controls installed and implemented in accordance with the approved erosion and sediment control plan and stormwater management plans?								\boxtimes					
	Are all control measures properly maintained in effective operating condition in accordance with good engineering practices and, where applicable, manufacturer specifications?							\boxtimes						
	3. Areas of offsite sediment deposition observed?								\boxtimes					
	<u>Comments:</u> Inspected the following resources: S-EF33, S-EF32, W-EF18 and S-II4. <u>Corrective Action:</u> N/A													

Deadline: N/A

The recommended corrective action deadline date applies to all conditions noted on this report unless otherwise noted. If listed condition(s) currently constitute non-compliance and/or corrective actions are not completed by the deadline, other enforcement actions may be issued to the entity responsible for ensuring compliance on the above project.

Inspector Signature:

Date: Thursday, August 15, 2024



STANDARDS & SPECIFICATIONS SITE INSPECTION REPORT LEVEL 1 (FIELD REPORT)

FIELD INSPECTION PHOTO LOG

Fig. 1 **Stream S-EF33:** Controls in place and functioning properly.



Fig. 2 **STA 12762+00:** Controls in place and functioning properly.



Fig. 3 **STA 13262+00:** Controls in place and functioning properly.



Fig. 4 **Stream S-II4:** Controls in place and functioning properly.

