

STANDARDS & SPECIFICATIONS SITE INSPECTION REPORT

LEVEL 1 (FIELD REPORT)

Project Name:	Mountain Valley Pipeline	S&S Program:	Mountain Valley Pipeline (SS027)
Inspector:	Marshall Willis	Inspection Date:	Tuesday, February 18, 2025
Project Contact:	Cory Chalmers Brian Clauto	Project Contact Email:	cchalmers@eqt.com bclauto@eqt.com
Spread I: Franklin County	STA 14928+52 - 14981+55 MVP-MLV-AR-33	Site Conditions:	Wet

ACTIVE STAGE OF CONSTRUCTION: (Check all that apply)													
	Tree Fellin	g		Clearing/Grubbing		Rough Grading		Trenching		Stri	nging/Welding		
	Lowering/Backfilling		Temp. Stabilization	\boxtimes	Perm. Stabilization	n 🗵	Dor	rmant					
									Yes	No	N/A		
	1.	Are controls installed and implemented in accordance with the approved erosion and sediment control plan and stormwater management plans?							\boxtimes				
	2. Are all control measures properly maintained in effective operating condition in accordance with good engineering practices and, where applicable, manufacturer specifications?							\boxtimes					
	3.	Areas of of	fsite	sediment deposition o	bserve	ed?				\boxtimes			
	Routin - Ineffec	e Maintena N/A etive Contro	nce: bls: (<u>ź</u>	he following resources (72-Hour Deadline from	om Not	ification)							
	Correc	ctive Actio	<u>on:</u> N	N/A									

Deadline: N/A

The recommended corrective action deadline date applies to all conditions noted on this report unless otherwise noted. If listed condition(s) currently constitute non-compliance and/or corrective actions are not completed by the deadline, other enforcement actions may be issued to the entity responsible for ensuring compliance on the above project.

Inspector Signature:

Date: Tuesday, February 18, 2025



STANDARDS & SPECIFICATIONS SITE INSPECTION REPORT LEVEL 1 (FIELD REPORT)

FIELD INSPECTION PHOTO LOG

Fig. 1 **Stream S-G15:** Controls in place and functioning properly.



Fig. 2 **STA 14980+00:** Controls in place and functioning properly.



Fig. 3 **STA 14957+00:** Controls in place and functioning properly.



Fig. 4

MVP-MLV-AR-33: Controls in place and functioning properly.

