

STANDARDS & SPECIFICATIONS SITE INSPECTION REPORT

LEVEL 1 (FIELD REPORT)

Project Name:	Mountain Valley Pipeline	S&S Program:	Mountain Valley Pipeline (SS027)
Inspector:	Marshall Willis	Inspection Date:	Monday, April 7, 2025
Project Contact:	Cory Chalmers Brian Clauto	Project Contact Email:	Cory.chalmers@eqt.com Brian.clauto@eqt.com
Spread I: Franklin County	STA 13748+30 - 13790+47 MVP-FR-300	Site Conditions:	Rainy

CT	CTIVE STAGE OF CONSTRUCTION: (Check all that apply)													
	Tree Felling		☐ Clearing/Grubbing			☐ Rough Grading		☐ Trenching		Stri	inging/Welding			
	Lowering/B	ng/Backfilling \square Final Grading \square Temp. Stabilization $oxtimes$ Perm. Stabilization			Doi	rmant								
									Yes	No	N/A			
	Are controls installed and implemented in accordance with the approved erosion and sediment control plan and stormwater management plans?								\boxtimes					
		Are all control measures properly maintained in effective operating condition in accordance with good engineering practices and, where applicable, manufacturer specifications?												
	3.	Areas of offsite sediment deposition observed?								\boxtimes				
	Routing Ineffec	e Maintena N/A	nce: ols: (<u>2</u>	(<u>72-Hour Deadline</u> fro 24-Hour Deadline fron	om Noti	,	nd, S-l	D23.						

Deadline: N/A

The recommended corrective action deadline date applies to all conditions noted on this report unless otherwise noted. If listed condition(s) currently constitute non-compliance and/or corrective actions are not completed by the deadline, other enforcement actions may be issued to the entity responsible for ensuring compliance on the above project.

Inspector Signature: __/

Date: Monday, April 7, 2025



STANDARDS & SPECIFICATIONS SITE INSPECTION REPORT LEVEL 1 (FIELD REPORT)

FIELD INSPECTION PHOTO LOG

Fig. 1

STA 13754+00: Controls in place and functioning properly.



Fig. 2 **Stream S-EF12:** Controls in place and functioning properly.



Fig. 3 **ATWS 569A:** Controls in place and functioning properly.



Fig. 4
STA 13784+00: Controls in place and functioning properly.

