

## STANDARDS & SPECIFICATIONS SITE INSPECTION REPORT

**LEVEL 1 (FIELD REPORT)** 

Project Name:	Mountain Valley Pipeline	S&S Program:	Mountain Valley Pipeline (SS027)
Inspector:	Marshall Willis	Inspection Date:	Tuesday, April 29, 2025
Project Contact:	Cory Chalmers Brian Clauto	Project Contact Email:	cory.chalmers@eqt.com brian.clauto@eqt.com
Spread I: Pittslyvania County	STA 15370+62 – 15480+67	Site Conditions:	Dry

_	Tree Felling		Clearing/Grubbing		Rough Grading		Trenching		<b>Stri</b>	nging/Welding
	rree relling		□ Clearing/Grubbling		Rough Grading	Ш	rrenching	Ш	Sui	rigirig/vveidiri
	Lowering/Backfilling		Final Grading		Temp. Stabilization	$\boxtimes$	Perm. Stabilization	$\boxtimes$	Dor	rmant
								Yes	No	N/A
		<ol> <li>Are controls installed and implemented in accordance with the approved erosion and sediment control plan and stormwater management plans?</li> <li>Are all control measures properly maintained in effective operating condition in accordance with good engineering practices and, where applicable, manufacturer specifications?</li> </ol>								
	3. Areas of	. Areas of offsite sediment deposition observed?							$\boxtimes$	
	Comments: Insp  Routine Mainter - N/A  Ineffective Cont - N/A	ance:	he following resources	s: S-G6	5, S-G5, S-G4, S-G3 ar	nd S-C	CC16.			
	Corrective Act	ion: N	N/A							

**Deadline:** N/A

The recommended corrective action deadline date applies to all conditions noted on this report unless otherwise noted. If listed condition(s) currently constitute non-compliance and/or corrective actions are not completed by the deadline, other enforcement actions may be issued to the entity responsible for ensuring compliance on the above project.

**Inspector Signature:** 

Date: Tuesday, April 29, 2025



## STANDARDS & SPECIFICATIONS SITE INSPECTION REPORT LEVEL 1 (FIELD REPORT)

## FIELD INSPECTION PHOTO LOG

Fig. 1

STA 15466+00: Controls in place and functioning properly.



Fig. 2 **Stream S-G4:** Controls in place and functioning properly.



Fig. 3 **STA 15379+00:** Controls in place and functioning properly.



Fig. 4
STA 15451+00: Controls in place and functioning properly.

