

COMPLAINT INVESTIGATION REPORT

Project Name:	Mountain Valley Pipeline	Inspector:	Marshall Willis
Inspection Date:	Friday, May 16, 2025	Project Contact:	Brian Clauto, Cory Chalmers
Spread H: Roanoke County	MVP-RO-287	Weather:	Dry

ACTIVE STAGE OF CONSTRUCTION: (Check all that apply)

- ☐ Tree Felling
 ☐ Clearing/Grubbing
 ☐ Grading
 ☐ Trenching
 ☐ Stringing/Welding
☐ Lowering/Backfilling
 ☐ Final Restoration
 ☐ Temp. Stabilization
 ☒ Perm. Stabilization
 ☐ Resource Crossing

- | | | Yes | No | N/A |
|----|---|-------------------------------------|-------------------------------------|--------------------------|
| 1. | Are controls installed and implemented in accordance with the approved erosion and sediment control plan and stormwater management plans? | <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> |
| 2. | Are all control measures properly maintained in effective operating condition in accordance with good engineering practices and, where applicable, manufacturer specifications? | <input type="checkbox"/> | <input checked="" type="checkbox"/> | <input type="checkbox"/> |
| 3. | Areas of offsite sediment deposition observed? | <input type="checkbox"/> | <input checked="" type="checkbox"/> | <input type="checkbox"/> |

Background: This investigation was conducted in response to complaint (IR#: 318928) submitted to PREP on May 15, 2025. The incident describes gravel displaced into wetlands along MVP-RO-287.

Observations:

1. No new impacts were found for Stream S-Z17 or W-IJ62. Old evidence of road material discharged to Wetland W-IJ62 was evident and was reported to MVP in the past. See Figure 3. Retrieval access was denied by the landowner at that time per MVP.
3. No additional sediment discharged off ROW was found during the inspection.
4. Corrective Action was noted during this inspection to repair P1 silt fence along the bridge of S-Z17 on MVP-RO-287.

Corrective Action: Maintain and install all controls per the approved PSS&S.

Deadline: Within 24-Hour of Notification

The recommended corrective action deadline date applies to all conditions noted on this report unless otherwise noted. If listed condition(s) currently constitute non-compliance and/or corrective actions are not completed by the deadline, other enforcement actions may be issued to the entity responsible for ensuring compliance on the above project.

Inspector Signature: Marshall Willis

Date: Friday, May 16, 2025

FIELD INSPECTION PHOTO LOG

Project Name: Mountain Valley Pipeline

Date: Friday, May 16, 2025

Figure 1: MVP-RO-287 – P1 SF maintenance required.



Figure 2: MVP-RO-287 – P1 SF maintenance required. Retrieve gravel.



Figure 3: MVP-RO-287 – Evidence of previous gravel washing from RO-287 impacting Wetland W-IJ62. Landowner previously refused access for clean up.

