

## COMPLAINT INVESTIGATION REPORT

Project Name:	Mountain Valley Pipeline	Inspector:	Marshall Willis
Inspection Date:	Friday, May 16, 2025	Project Contact:	Brian Clauto, Cory Chalmers
Spread H: Roanoke County	STA 12955+00 to 12960+00	Weather:	Dry

**ACTIVE STAGE OF CONSTRUCTION:** (Check all that apply)

- ☐ Tree Felling
 ☐ Clearing/Grubbing
 ☐ Grading
 ☐ Trenching
 ☐ Stringing/Welding  
☐ Lowering/Backfilling
 ☐ Final Restoration
 ☐ Temp. Stabilization
 ☒ Perm. Stabilization
 ☐ Resource Crossing

- |    |   | Yes                                 | No                                  | N/A                      |
|----|---|-------------------------------------|-------------------------------------|--------------------------|
| 1. | Are controls installed and implemented in accordance with the approved erosion and sediment control plan and stormwater management plans?                                       | <input checked="" type="checkbox"/> | <input type="checkbox"/>            | <input type="checkbox"/> |
| 2. | Are all control measures properly maintained in effective operating condition in accordance with good engineering practices and, where applicable, manufacturer specifications? | <input type="checkbox"/>            | <input checked="" type="checkbox"/> | <input type="checkbox"/> |
| 3. | Areas of offsite sediment deposition observed?  | <input type="checkbox"/>            | <input checked="" type="checkbox"/> | <input type="checkbox"/> |

**Background:** This investigation was conducted in response to complaint (IR#: 318927) submitted to PREP on May 15, 2025. The incident describes "excessive erosion, rutting of road" within the MVP ROW.

**Observations:**

1. No sedimentation was found to be impacting Stream S-Y7, S-Y8, S-Y9 (spring box) or Wetland W-Y2 along the ROW.
3. No sediment discharged off ROW was found during the inspection.
4. Controls were installed and functioning properly at the time of inspection.
5. Erosion was noted along the landowner's roadway though the ROW at approx. STA 12957+00. Corrective Action was assigned to repair rilling and restabilize this area.
6. MVP to work with Landowner to repair roadbed or add stone as needed.

**Corrective Action:** Maintain and install all controls per the approved PSS&S.

**Deadline:** Within 72-Hour of Notification

The recommended corrective action deadline date applies to all conditions noted on this report unless otherwise noted. If listed condition(s) currently constitute non-compliance and/or corrective actions are not completed by the deadline, other enforcement actions may be issued to the entity responsible for ensuring compliance on the above project.

**Inspector Signature:** Marshall Willis

**Date:** Friday, May 16, 2025

# FIELD INSPECTION PHOTO LOG

**Project Name:** Mountain Valley Pipeline

**Date:** Friday, May 16, 2025

**Figure 1: STA 12957+00 – Repair rilling and restabilize.**



**Figure 2: STA 12957+00 – Repair rilling and restabilize.**



**Figure 3: STA 12957+00 – Repair rilling and restabilize.**

