

STANDARDS & SPECIFICATIONS SITE INSPECTION REPORT

LEVEL 1 (FIELD REPORT)

Project Name:	Mountain Valley Pipeline	S&S Program:	Mountain Valley Pipeline (SS027)
Inspector:	Marshall Willis	Inspection Date:	Friday, July 18, 2025
Project Contact:	Cory Chalmers Brian Clauto	Project Contact Email:	cory.chalmers@eqt.com brian.clauto@eqt.com
Spread I: Franklin County	STA 13888+27 - 13916+12	Site Conditions:	Wet

ACTI	ACTIVE STAGE OF CONSTRUCTION: (Check all that apply)													
	Tree Felling	g		Clearing/Grubbing		Rough Grading		Trenching		Strin	ging/Welding			
	Lowering/B	Backfilling		Final Grading		Temp. Stabilization	\boxtimes	Perm. Stabilization	n 🗌 Other		er			
									Yes	No	N/A			
	Are controls installed and implemented in accordance with the approved erosion and sediment control plan and stormwater management plans?							\boxtimes						
	Are all control measures properly maintained in effective operating condition in accordance with good engineering practices and, where applicable, manufacturer specifications?								\boxtimes					
	3. Areas of offsite sediment deposition observed?									\boxtimes				
	Routin - Ineffec -	ents: Insper e Maintena N/A tive Contro N/A	ince (ols (2	4-Hr):	s: W-C	D5 and S-II2.								
Deadline: N/A														
The recommended corrective action deadline date applies to all conditions noted on this report unless otherwise noted. If listed condition(s) currently constitute non-compliance and/or corrective actions are not completed by the deadline, other enforcement actions may be issued to the entity responsible for ensuring compliance on the above project.														
Inspector Signature: Malul Willtr														
Date	Date: Friday, July 18, 2025													



STANDARDS & SPECIFICATIONS SITE INSPECTION REPORT LEVEL 1 (FIELD REPORT)

FIELD INSPECTION PHOTO LOG

Fig. 1 **STA 13890+00:** Controls in place and functioning properly.



Fig. 2 **STA 13900+00:** Controls in place and functioning properly.



Fig. 3 **STA 13907+00:** Controls in place and functioning properly.



Fig. 4
STA 13915+00: Controls in place and functioning properly.

