

FIELD INSPECTION REPORT

Project Name:	Mountain Valley Pipeline	Inspector:	Marshall Willis
Inspection Date:	Thursday, September 10, 2020	Project Contact:	Brian Clauto, Cory Chalmers
Spread H: Roanoke County	STA 12687+00 – 12703+00 STA 12994+00 – 13020+00 MVP-RO-280	Weather:	Rainy

ACTIVE STAGE OF CONSTRUCTION: (Check all that apply)

- | | | | | |
|---|--|--|--|---|
| ☐ Tree Felling | ☐ Clearing/Grubbing | ☐ Grading | ☐ Trenching | ☐ Stringing/Welding |
| ☐ Lowering/Backfilling | ☐ Final Restoration | ☐ Temp. Stabilization | ☐ Perm. Stabilization | ☒ Dormant |

- | | Yes | No | N/A |
|--|-------------------------------------|-------------------------------------|--------------------------|
| 1. Are controls installed and implemented in accordance with the approved erosion and sediment control plan and stormwater management plans? | ☒ | ☐ | ☐ |
| 2. Are all control measures properly maintained in effective operating condition in accordance with good engineering practices and, where applicable, manufacturer specifications? | ☒ | ☐ | ☐ |
| 3. Areas of offsite sediment deposition observed? | ☐ | ☒ | ☐ |

Comments: Inspected the following resources: N/A.

Recommended Corrective Action: N/A

Deadline: N/A

The recommended corrective action deadline date applies to all conditions noted on this report unless otherwise noted. If listed condition(s) currently constitute non-compliance and/or corrective actions are not completed by the deadline, other enforcement actions may be issued to the entity responsible for ensuring compliance on the above project.

Inspector Signature: Marshall Willis

Date: Thursday, September 10, 2020

FIELD INSPECTION PHOTO LOG

Project Name: Mountain Valley Pipeline

Date: Thursday, September 10, 2020

Figure 1: STA 13012+00 – Controls in place and functioning properly.

⊗ 302°NW (T) ● 37°7'33"N, 80°7'31"W ±16ft ▲ 2692ft



Figure 2: STA 13018+00 – Controls in place and functioning properly.

⊗ 102°E (T) ● 37°7'31"N, 80°7'25"W ±32ft ▲ 2727ft



Figure 3: STA 12685+00 – Controls in place and functioning properly.

⊗ 267°W (T) ● 37°11'33"N, 80°9'32"W ±32ft ▲ 3695ft



Figure 4: STA 12692+00 – Controls in place and functioning properly.

⊗ 114°SE (T) ● 37°11'28"N, 80°9'24"W ±16470ft ▲ 3694ft

