

FIELD INSPECTION REPORT

Project Name:	Mountain Valley Pipeline	Inspector:	Matthew Grant
Inspection Date:	Tuesday, February 18, 2020	Project Contact:	Brian Clauto,
Spread H:	MP 237.2-235.7 ATWS 645	Weather:	Rainy
Montgomery			

ACTIVE STAGE OF CONSTRUCTION: (Check all that apply)

- | | | | | |
|---|--|--|--|---|
| ☐ Tree Felling | ☐ Clearing/Grubbing | ☐ Grading | ☐ Trenching | ☐ Stringing/Welding |
| ☐ Lowering/Backfilling | ☐ Final Grading | ☐ Temp. Stabilization | ☐ Perm. Stabilization | ☒ Dormant |

- | | | Yes | No | N/A |
|----|---|-------------------------------------|-------------------------------------|--------------------------|
| 1. | Are controls installed and implemented in accordance with the approved erosion and sediment control plan and stormwater management plans? | ☒ | ☐ | ☐ |
| 2. | Are all control measures properly maintained in effective operating condition in accordance with good engineering practices and, where applicable, manufacturer specifications? | ☒ | ☐ | ☐ |
| 3. | Areas of offsite sediment deposition observed? | ☐ | ☒ | ☐ |

- Comments: Inspected the following resources: S-EF19, W-KL58, S-CD12b
 - ECD's were in place at crossings and appeared to be functioning.
 - Due site conditions near St12529, plastic sheeting has been installed on stockpile slope; additional controls are planned once site conditions improve.

Routine Maintenance: (72-Hour Deadline from Notification)

- N/A


Ineffective Controls: (24-Hour Deadline from Notification)

- N/A

Recommended Corrective Action: N/A

Deadline: N/A

The recommended corrective action deadline date applies to all conditions noted on this report unless otherwise noted. If listed condition(s) currently constitute non-compliance and/or corrective actions are not completed by the deadline, other enforcement actions may be issued to the entity responsible for ensuring compliance on the above project.

Inspector Signature: _____  _____


Date: Tuesday, February 18, 2020

FIELD INSPECTION PHOTO LOG

Project Name: Mountain Valley Pipeline

Date: Tuesday, February 18, 2020

- Figure 1: Near St12529+00 plastic sheeting has temporarily been installed.



- Figure 2: Designated stream crossing S-EF19, ECD's are in place and appear to be functioning.



- Figure 3: Slopes leading to designated stream S-EF19 are stabilized and ECD's are in place.



- Figure 4: Slopes leading to the CWD near St12501 are stabilized and ECD's are in place.

