

FIELD INSPECTION

Project Name:	Mountain Valley Pipeline	Inspector:	Matthew Grant
Inspection Date:	Thursday, December 12, 2019	Project Contact:	Brian Clauto
Spread: Franklin Co. MP 253.9- 254.1 ATWS 1351 MP258- 258.8 MP 256.1	Spread I	Weather (Wet/Dry/Rain):	Dry

STAGE OF CONSTRUCTION: (Check all that apply)

- ☐ Clearing

☐ Rough Grading

☐ Trench Excavation

☐ Pipe Assembly, Testing & Installation

☐ Backfilling and Grade Restoration

☐ Final Grading & Stabilization

☒ Other: Dormant

- | | | Yes | No | N/A |
|---|---|-------------------------------------|-------------------------------------|--------------------------|
| 1 | Are controls installed and implemented in accordance with the approved erosion and sediment control plan and stormwater management plans? | ☒ | ☐ | ☐ |
| 2 | Are all control measures properly maintained in effective operating condition in accordance with good engineering practices and, where applicable, manufacturer specifications? | ☒ | ☐ | ☐ |
| 3 | Areas of offsite sediment deposition were observed? | ☐ | ☒ | ☐ |

Comments:

- Inspected designated streams and wetlands included: S-IJ4, S-IJ10, S-GH2, S-KL2
- ECD's inspected were in place at designated crossings.
- St13425+00 slope requires additional stabilization.

Recommend Corrective Action: Maintain all controls per the approved plan and annual standards & spec.

Deadline: Within 24hr notification

The recommended corrective action deadline date applies to all conditions noted on this report unless otherwise noted. If listed condition(s) currently constitute non-compliance and/or corrective actions are not completed by the deadline, other enforcement actions may be issued to the entity responsible for ensuring compliance on the above project.

Inspector Signature: Matthew Grant Date: 12-30-19

FIELD INSPECTION PHOTO LOG

Project Name: Mountain Valley Pipeline

Date: Thursday, December 12, 2019


- Fig. 1. Designated stream crossing S-IJ4, slope requires additional stabilization.



- Fig. 2. Designated stream crossing S-IJ4, slope requires additional stabilization.



- Fig. 3. Designated stream crossing S-KL32, ECD's in place and functioning. Farming activities are ongoing in this area.



- Fig. 4. Designated stream crossing S-IJ 10, ECD's in place and functioning. Farming activities are ongoing in this area.

