

FIELD INSPECTION

Project Name:	Mountain Valley Pipeline	Inspector:	Matthew Grant
Inspection Date:	Thursday, November 7, 2019	Project Contact:	Brian Clauto
Spread: Franklin Co. MP251 ATWS 1055 MP251.9-252 ATWS 1412 MP254.3 FR 293.02 ATWS 1342 Pittsylvania Co. MP 286- 286.3 ATWS 384, 384A	Spread I	Weather (Wet/Dry/Rain):	Dry

STAGE OF CONSTRUCTION: (Check all that apply)

- ☐ Clearing

☐ Rough Grading

☐ Trench Excavation

☐ Pipe Assembly, Testing & Installation

☐ Backfilling and Grade Restoration

☐ Final Grading & Stabilization

☒ Other: Dormant

- | | | Yes | No | N/A |
|---|---|-------------------------------------|-------------------------------------|--------------------------|
| 1 | Are controls installed and implemented in accordance with the approved erosion and sediment control plan and stormwater management plans? | ☒ | ☐ | ☐ |
| 2 | Are all control measures properly maintained in effective operating condition in accordance with good engineering practices and, where applicable, manufacturer specifications? | ☒ | ☐ | ☐ |
| 3 | Areas of offsite sediment deposition were observed? | ☐ | ☒ | ☐ |

Comments:

- Inspected designated streams and wetlands included: S-II4, S-GH-7, S-A5, S-A6, W-A5,
- ECD's inspected were in place at designated crossings.

Recommend Corrective Action: N/A

Deadline: N/A

The recommended corrective action deadline date applies to all conditions noted on this report unless otherwise noted. If listed condition(s) currently constitute non-compliance and/or corrective actions are not completed by the deadline, other enforcement actions may be issued to the entity responsible for ensuring compliance on the above project.

Inspector Signature: Matthew Grant Date: 11-12-19

FIELD INSPECTION PHOTO LOG

Project Name: Mountain Valley Pipeline

Date: Thursday, November 7, 2019

- Fig. 1. At designated stream S-II4, controls in place and functioning.



- Fig. 2 At designated stream S-GH7, controls in place and functioning.



- Fig. 3 At designated stream S-A5, controls in place and functioning.



- Fig. 4 At designated wetland W-A5, controls in place and functioning, escaped sediment has been removed.

