

FIELD INSPECTION

Project Name:	Mountain Valley Pipeline	Inspector:	Marshall Willis
Inspection Date:	Wednesday, October 23, 2019	Project Contact:	Brian Clauto, Cory Chalmers
Spread I: Franklin County	STA 13996+58 – 14009+81 STA 13892+55 – 13917+50 STA 13676+85 – 13704+00 STA 13830+00 – 13820+00 MVP-FR-300/302/306.02	Weather (Wet/Dry/Rain):	Wet

STAGE OF CONSTRUCTION: (Check all that apply)

- ☐ Clearing

☐ Rough Grading

☐ Trench Excavation

☐ Pipe Assembly, Testing & Installation

☐ Backfilling and Grade Restoration

☐ Final Grading & Stabilization

☒ Other: Dormant

- | | | Yes | No | N/A |
|---|---|-------------------------------------|-------------------------------------|--------------------------|
| 1 | Are controls installed and implemented in accordance with the approved erosion and sediment control plan and stormwater management plans? | ☒ | ☐ | ☐ |
| 2 | Are all control measures properly maintained in effective operating condition in accordance with good engineering practices and, where applicable, manufacturer specifications? | ☒ | ☐ | ☐ |
| 3 | Areas of offsite sediment deposition were observed? | ☐ | ☒ | ☐ |

Comments: Inspected the following resources: S-KL36, S-E28, S-E28, S-E28, S-E29, W-E7, W-E8 and S-II2.

Recommended Corrective Action: N/A

Deadline: Within 24-hr notification

The recommended corrective action deadline date applies to all conditions noted on this report unless otherwise noted. If listed condition(s) currently constitute non-compliance and/or corrective actions are not completed by the deadline, other enforcement actions may be issued to the entity responsible for ensuring compliance on the above project.

Inspector Signature: *Marshall Willis*

Date: 10/23/2019

FIELD INSPECTION PHOTO LOG

Project Name: Mountain Valley Pipeline

Date: Wednesday, October 23, 2019

Fig. 1: **STA 14000+00** – Controls in place. Area stabilized with hydro-mulch.



Fig. 2: **STA 13906+55** – Controls in place. Area stabilized with straw and erosion blanket.



Fig. 3: **Stream S-E28** – Controls in place along Teels Creek.



Fig. 4: **STA 13820+00** – Controls in place. Area stabilized.

