

FIELD INSPECTION

Project Name:	Mountain Valley Pipeline	Inspector:	Marshall Willis
Inspection Date:	Monday, October 7, 2019	Project Contact:	Brian Clauto, Cory Chalmers
Spread I: Pittsylvania County	H602 STA 15941+75 – 16027+46	Weather (Wet/Dry/Rain):	Dry

STAGE OF CONSTRUCTION: (Check all that apply)

- ☐ Clearing
 ☐ Rough Grading
 ☐ Trench Excavation
 ☐ Pipe Assembly, Testing & Installation
☐ Backfilling and Grade Restoration
 ☐ Final Grading & Stabilization
 ☒ Other: Dormant

- | | | Yes | No | N/A |
|---|---|-------------------------------------|-------------------------------------|--------------------------|
| 1 | Are controls installed and implemented in accordance with the approved erosion and sediment control plan and stormwater management plans? | ☒ | ☐ | ☐ |
| 2 | Are all control measures properly maintained in effective operating condition in accordance with good engineering practices and, where applicable, manufacturer specifications? | ☐ | ☒ | ☐ |
| 3 | Areas of offsite sediment deposition were observed? | ☐ | ☒ | ☐ |

Comments: Inspected the following resources: W-H1, S-H3, W-H2, W-H3, S-H5, W-MM3, S-OO1, W-IJ22, S-EF26, S-H44 and S-H41.

- S-H42 to Williams Station: Stockpile stabilization needed.
- H602 Line STA 12+65: CFS maintenance needed.
- Stream S-OO1: Stabilization needed on both sides of stream crossing.
- STA 15970+00: CFS maintenance needed.

Recommended Corrective Action: Maintain and install all controls per the approved plans and PSS&S.

Deadline: Within 24-hr notification

The recommended corrective action deadline date applies to all conditions noted on this report unless otherwise noted. If listed condition(s) currently constitute non-compliance and/or corrective actions are not completed by the deadline, other enforcement actions may be issued to the entity responsible for ensuring compliance on the above project.

Inspector Signature: Marshall Willis

Date: 10/07/2019

FIELD INSPECTION PHOTO LOG

Project Name: Mountain Valley Pipeline

Date: Monday, October 7, 2019

Fig. 1: **S-H42 to Williams Station** – Stockpile stabilization needed.



Fig. 2: **H602 Line STA 12+65** – CFS maintenance needed.



Fig. 3: **Stream S-001** – Stabilization needed on both sides of stream crossing.



Fig. 4: **STA 15970+00** – CFS maintenance needed.

