

FIELD INSPECTION

Project Name:	Mountain Valley Pipeline	Inspector:	Matthew Grant
Inspection Date:	Wednesday, June 26, 2019	Project Contact:	Brian Clauto
Spread: Franklin County AR32 MP269 MP265.5-266.5 Pittsylvania Co. MP 301 15419-159641	Spread I	Weather (Wet/Dry/Rain):	Dry

STAGE OF CONSTRUCTION: (Check all that apply)

- ☐ Clearing

☐ Rough Grading

☐ Trench Excavation

☐ Pipe Assembly, Testing & Installation

☐ Backfilling and Grade Restoration

☐ Final Grading & Stabilization

☒ Other: Dormant

- | | | Yes | No | N/A |
|---|---|-------------------------------------|-------------------------------------|--------------------------|
| 1 | Are controls installed and implemented in accordance with the approved erosion and sediment control plan and stormwater management plans? | ☒ | ☐ | ☐ |
| 2 | Are all control measures properly maintained in effective operating condition in accordance with good engineering practices and, where applicable, manufacturer specifications? | ☒ | ☐ | ☐ |
| 3 | Areas of offsite sediment deposition were observed? | ☐ | ☒ | ☐ |

Comments:

- Streams / wetlands inspected included: S-C19,S-F11, W-H2, W-H3, S-H5, S-YZ4, S-KL41
- ECD controls are in place and functioning at the wetlands and streams.

Recommended Corrective Action: N/A

Deadline: N/A

The recommended corrective action deadline date applies to all conditions noted on this report unless otherwise noted. If listed condition(s) currently constitute non-compliance and/or corrective actions are not completed by the deadline, other enforcement actions may be issued to the entity responsible for ensuring compliance on the above project.


Inspector Signature: Matthew Grant Date: 7/26/19

FIELD INSPECTION PHOTO LOG

Project Name: Mountain Valley Pipeline

Date: Wednesday, June 26, 2019

- Fig. 1 ECD are in place at designated stream S-C19



- Fig. 2 At designated stream S-F11, bridge debris has been removed.



- Fig. 3 Mat crossing material has been repaired at designated stream and wetland crossings W-H2, W-H3 and S-H5



- Fig. 4 ECD controls are in place at designated stream S-KL41

