

FIELD INSPECTION

Project Name:	Mountain Valley Pipeline	Inspector:	Marshall Willis
Inspection Date:	Tuesday, April 9, 2019	Project Contact:	Brian Clauto
Spread I: Franklin County	STA 14333+27 – 14411+04	Weather (Wet/Dry/Rain):	Wet

STAGE OF CONSTRUCTION: (Check all that apply)

- ☐ Clearing
 ☐ Rough Grading
 ☐ Trench Excavation
 ☐ Pipe Assembly, Testing & Installation
☐ Backfilling and Grade Restoration
 ☐ Final Grading & Stabilization
 ☒ Other: Dormant

- | | Yes | No | N/A |
|---|-------------------------------------|-------------------------------------|--------------------------|
| 1 Are controls installed and implemented in accordance with the approved erosion and sediment control plan and stormwater management plans? | ☐ | ☒ | ☐ |
| 2 Are all control measures properly maintained in effective operating condition in accordance with good engineering practices and, where applicable, manufacturer specifications? | ☐ | ☒ | ☐ |
| 3 Areas of offsite sediment deposition were observed? | ☒ | ☐ | ☐ |

Comments: Inspected the following resources: S-A41, S-WA12, S-A38, S-A40, W-DD1 and S-A36.

STA 14333+34: Stabilize area adjacent to RCE.
 STA 14354+10: Remove sediment on bridge crossing of S-A40/A38.
 STA 14354+10: Stabilize CIS/GAS S-A38 & S-A40.
 STA 14354+10: Bridge sideboards do not extend past S-A40.
 STA 14354+10: Sediment impacting S-A40.
 STA 14382+00 to STA 14383+00: Stabilize ROW around CWDs.
 STA 14389+00: ATWS 622 – Repair P1.
 STA 14391+47: Repair P1.
 STA 14394+00: Sediment off ROW.
 STA 14411+04: MVP-FR-315: Stabilize area adjacent to access road.

Recommended Corrective Action: Maintain and install all controls per the approved plan and specs.

Deadline: Within 24-hr notification

The recommended corrective action deadline date applies to all conditions noted on this report unless otherwise noted. If listed condition(s) currently constitute non-compliance and/or corrective actions are not completed by the deadline, other enforcement actions may be issued to the entity responsible for ensuring compliance on the above project.

Inspector Signature: Marshall Willis

Date: 04/09/2019

FIELD INSPECTION PHOTO LOG

Project Name: Mountain Valley Pipeline

Date: Tuesday, April 9, 2019

Fig. 1: **STA 14333+34** – Stabilize area adjacent to RCE along Golden View Road.



Fig. 2: **STA 14354+10** – S-A38/A40: Remove sediment on temp. crossing.



Fig. 3: **STA 14354+10** – S-A40: No stabilization on CIS or GAS of S-38/40. No Earth-Guard present.



Fig. 4: **STA 14354+10** – S-A40: No sideboards.



FIELD INSPECTION PHOTO LOG

Project Name: Mountain Valley Pipeline

Date: Tuesday, April 9, 2019

Fig. 5: **STA 14354+10** – S-A40: Sediment impacting stream.



Fig. 6: **STA 14382+00 through 14383+00** – Stabilize area. No Earth-Guard present.



Fig. 7: **STA 14389+00** – Repair P1.



Fig. 8: **STA 14391+47** – Repair P1.



FIELD INSPECTION PHOTO LOG

Project Name: Mountain Valley Pipeline

Date: Tuesday, April 9, 2019

Fig. 9: **STA 14393+00** – Sediment off ROW.



Fig. 10: **STA 14411+04** – MVP-FR-315: Stabilize along shoulder.

