

FIELD INSPECTION

Project Name:	Mountain Valley Pipeline	Inspector:	Marshall Willis
Inspection Date:	Thursday, May 30, 2019	Project Contact:	Brian Clauto
Spread I: Franklin County Pittsylvania County	STA 14062+17 – 14171+36 STA 14981+55 – 15063+85	Weather (Wet/Dry/Rain):	Dry

STAGE OF CONSTRUCTION: (Check all that apply)

- ☐ Clearing

☐ Rough Grading

☐ Trench Excavation

☐ Pipe Assembly, Testing & Installation

☐ Backfilling and Grade Restoration

☐ Final Grading & Stabilization

☒ Other: Dormant

- | | | Yes | No | N/A |
|---|---|-------------------------------------|-------------------------------------|--------------------------|
| 1 | Are controls installed and implemented in accordance with the approved erosion and sediment control plan and stormwater management plans? | ☒ | ☐ | ☐ |
| 2 | Are all control measures properly maintained in effective operating condition in accordance with good engineering practices and, where applicable, manufacturer specifications? | ☐ | ☒ | ☐ |
| 3 | Areas of offsite sediment deposition were observed? | ☐ | ☒ | ☐ |

Comments: Inspected the following resources: S-EF48, S-KL41, S-C8, S-KL51, S-D7, S-D3, S-D4, W-D3, S-D2 and S-D1-INT.

STA 14105+64: Repair undermined P1.

Recommended Corrective Action: Maintain and install all controls per the approved plan and specs.

Deadline: Within 24-hr notification

The recommended corrective action deadline date applies to all conditions noted on this report unless otherwise noted. If listed condition(s) currently constitute non-compliance and/or corrective actions are not completed by the deadline, other enforcement actions may be issued to the entity responsible for ensuring compliance on the above project.

Inspector Signature: *Marshall Willis*

Date: 05/30/2019

FIELD INSPECTION PHOTO LOG

Project Name: Mountain Valley Pipeline

Date: Thursday, May 30, 2019

Fig. 1: **STA 14063+00** – Controls in place. Area stabilized.



Fig. 2: **STA 14105+64** – P1 undermined above S-KL41.



Fig. 3: **STA 15003+33** – Controls in place. Area stabilized.



Fig. 4: **STA 15057+76** – Controls in place. Area stabilized.

