

FIELD INSPECTION REPORT

Project Name:	Mountain Valley Pipeline	Inspector:	Marshall Willis
Inspection Date:	Wednesday, December 15, 2021	Project Contact:	Brian Clauto, Cory Chalmers
Spread I: Pittsylvania County	STA 16002+97 – 16027+00 Transco Station H-602/H-603 Lines	Weather:	Dry

ACTIVE STAGE OF CONSTRUCTION: (Check all that apply)

- | | | | | |
|---|--|--|--|---|
| <input type="checkbox"/> Tree Felling | <input type="checkbox"/> Clearing/Grubbing | <input type="checkbox"/> Grading | <input type="checkbox"/> Trenching | <input type="checkbox"/> Stringing/Welding |
| <input type="checkbox"/> Lowering/Backfilling | <input type="checkbox"/> Final Restoration | <input type="checkbox"/> Temp. Stabilization | <input type="checkbox"/> Perm. Stabilization | <input checked="" type="checkbox"/> Dormant |

- | | | Yes | No | N/A |
|----|---|-------------------------------------|-------------------------------------|--------------------------|
| 1. | Are controls installed and implemented in accordance with the approved erosion and sediment control plan and stormwater management plans? | <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> |
| 2. | Are all control measures properly maintained in effective operating condition in accordance with good engineering practices and, where applicable, manufacturer specifications? | <input type="checkbox"/> | <input checked="" type="checkbox"/> | <input type="checkbox"/> |
| 3. | Areas of offsite sediment deposition observed? | <input type="checkbox"/> | <input checked="" type="checkbox"/> | <input type="checkbox"/> |

Comments: Inspected the following resources: S-EF26, S-H44 and S-H42.

Routine Maintenance: (72-Hour Deadline from Notification)

- Transco Station: Re-stabilize basin embankment.
- Transco Station: Re-stabilize berm around ST-2.
- Transco Station: Repair geotextile underlayment in channel CH-I.
- Transco Station: Re-stabilize area around soil stockpiles.

Recommended Corrective Action: Maintain and install all controls per the approved PSS&S.

Deadline: Within 72-Hour of Notification

The recommended corrective action deadline date applies to all conditions noted on this report unless otherwise noted. If listed condition(s) currently constitute non-compliance and/or corrective actions are not completed by the deadline, other enforcement actions may be issued to the entity responsible for ensuring compliance on the above project.

Inspector Signature: 

Date: Wednesday, December 15, 2021

FIELD INSPECTION PHOTO LOG

Project Name: Mountain Valley Pipeline

Date: Wednesday, December 15, 2021

Figure 1: Transco Station – Re-stabilize basin embankment.
BRG: 11°N (T) LAT: 36.831578 LON: -79.344081 ±16ft ALT: 633ft



Figure 2: Transco Station – Re-stabilize berm around ST-2.
BRG: 5°N (T) LAT: 36.832117 LON: -79.344105 ±16ft ALT: 644ft



Figure 3: Transco Station – Repair geotextile underlayment in channel CH-I.
BRG: 354°N (T) LAT: 36.832511 LON: -79.343409 ±16ft ALT: 660ft



Figure 4: Transco Station – Re-stabilize area near soil stockpiles.
BRG: 289°W (T) LAT: 36.832831 LON: -79.343836 ±16ft ALT: 637ft

