

FIELD INSPECTION REPORT

Project Name:	Mountain Valley Pipeline	Inspector:	Marshall Willis
Inspection Date:	Friday, January 28, 2022	Project Contact:	Brian Clauto, Cory Chalmers
Spread H: Roanoke County	STA 12992+00 – 13018+00	Weather:	Snow

ACTIVE STAGE OF CONSTRUCTION: (Check all that apply)

- ☐ Tree Felling
 ☐ Clearing/Grubbing
 ☐ Grading
 ☐ Trenching
 ☐ Stringing/Welding
☐ Lowering/Backfilling
 ☐ Final Restoration
 ☐ Temp. Stabilization
 ☐ Perm. Stabilization
 ☒ Dormant

- | | | Yes | No | N/A |
|----|---|-------------------------------------|-------------------------------------|--------------------------|
| 1. | Are controls installed and implemented in accordance with the approved erosion and sediment control plan and stormwater management plans? | ☒ | ☐ | ☐ |
| 2. | Are all control measures properly maintained in effective operating condition in accordance with good engineering practices and, where applicable, manufacturer specifications? | ☒ | ☐ | ☐ |
| 3. | Areas of offsite sediment deposition observed? | ☐ | ☒ | ☐ |

Comments: Inspected the following resources: W-B24-PSS.

Recommended Corrective Action: N/A

Deadline: N/A

The recommended corrective action deadline date applies to all conditions noted on this report unless otherwise noted. If listed condition(s) currently constitute non-compliance and/or corrective actions are not completed by the deadline, other enforcement actions may be issued to the entity responsible for ensuring compliance on the above project.

Inspector Signature:



Date: Friday, January 28, 2022

FIELD INSPECTION PHOTO LOG

Project Name: Mountain Valley Pipeline

Date: Friday, January 28, 2022

Figure 1: STA 13012+00 – Controls in place and functioning properly.

BRG: 342°N (T) **LAT:** 37.125746 **LON:** -80.126193 ±1715ft **ALT:** 3019ft



Figure 2: STA 13017+00 – Controls in place and functioning properly.

BRG: 91°E (T) **LAT:** 37.125427 **LON:** -80.123500 ±32ft **ALT:** 2733ft



Figure 3: STA 12995+00 – Controls in place and functioning properly.

BRG: 88°E (T) **LAT:** 37.129445 **LON:** -80.130268 ±213ft **ALT:** 2897ft



Figure 4: Wetland W-B24-PSS – Controls in place and functioning properly along wetland W-B24-PSS.

BRG: 283°W (T) **LAT:** 37.128460 **LON:** -80.130681 ±16ft **ALT:** 2673ft

