

FIELD INSPECTION REPORT

Project Name:	Mountain Valley Pipeline	Inspector:	Marshall Willis
Inspection Date:	Wednesday, January 26, 2022	Project Contact:	Brian Clauto, Cory Chalmers
Spread I: Franklin County	STA 14719+00 – 14758+50 MVP-FR-321	Weather:	Snow

ACTIVE STAGE OF CONSTRUCTION: (Check all that apply)

- ☐ Tree Felling
 ☐ Clearing/Grubbing
 ☐ Grading
 ☐ Trenching
 ☐ Stringing/Welding
☐ Lowering/Backfilling
 ☐ Final Restoration
 ☐ Temp. Stabilization
 ☐ Perm. Stabilization
 ☒ Dormant

- | | | Yes | No | N/A |
|----|---|-------------------------------------|-------------------------------------|--------------------------|
| 1. | Are controls installed and implemented in accordance with the approved erosion and sediment control plan and stormwater management plans? | ☒ | ☐ | ☐ |
| 2. | Are all control measures properly maintained in effective operating condition in accordance with good engineering practices and, where applicable, manufacturer specifications? | ☒ | ☐ | ☐ |
| 3. | Areas of offsite sediment deposition observed? | ☐ | ☒ | ☐ |

Comments: Inspected the following resources: S-A18, S-A19/H26, S-A20, S-H27 and S-A22.

Recommended Corrective Action: N/A

Deadline: N/A

The recommended corrective action deadline date applies to all conditions noted on this report unless otherwise noted. If listed condition(s) currently constitute non-compliance and/or corrective actions are not completed by the deadline, other enforcement actions may be issued to the entity responsible for ensuring compliance on the above project.

Inspector Signature:



Date: Wednesday, January 26, 2022

FIELD INSPECTION PHOTO LOG

Project Name: Mountain Valley Pipeline

Date: Wednesday, January 26, 2022

Figure 1: STA 14720+00 – Controls in place and functioning properly.

BRG: 121°SE (T) **LAT:** 36.988098 **LON:** -79.702241 ±213ft **ALT:** 926ft



Figure 2: STA 14729+00 – Controls in place and functioning properly.

BRG: 92°E (T) **LAT:** 36.987957 **LON:** -79.698963 ±98ft **ALT:** 802ft



Figure 3: STA 14739+00 – Controls in place and functioning properly.

BRG: 286°W (T) **LAT:** 36.986520 **LON:** -79.695806 ±16ft **ALT:** 1013ft



Figure 4: STA 14755+00 – Controls in place and functioning properly.

BRG: 300°NW (T) **LAT:** 36.984407 **LON:** -79.691028 ±213ft **ALT:** 930ft

